

**IN THE UNITED STATES DISTRICT COURT  
FOR THE NORTHERN DISTRICT OF ILLINOIS**

PATRICK SANCHEZ, MARK  
STAUBER, and SALLY STAUBER,  
JACOB ROSS-DEMMIN, and JENNIFER  
HERRINGTON on behalf of themselves  
and all others similarly situated,

Plaintiffs,

v.

GENERAL MOTORS LLC, a Delaware  
limited liability company,

Defendant.

Civil Action No. \_\_\_\_\_

**CLASS ACTION COMPLAINT AND  
COMPLAINT FOR DAMAGES**

**Jury Trial Demanded**

Plaintiffs Patrick Sanchez, Mark Stauber, Sally Stauber, Jacob Ross-Demmin, and Jennifer Herrington (collectively, “Plaintiffs”), acting on behalf of themselves and all others similarly situated, bring this action for damages and equitable relief against Defendant General Motors LLC (“GM”).

**NATURE OF THE CASE**

1. GM designed, manufactured, distributed, marketed, sold, and leased Model Year 2010-2017 Chevrolet Equinox and GMC Terrain vehicles with 2.4-liter engines (“Class Vehicles” or “Vehicles”) to Plaintiffs and Class Members. These engines were denominated within GM as the “LAF” and “LEA” engines (also referred to herein as the “EcoTech 2.4L” engine).

2. Engine oil, or motor oil, functions as an essential lubricant for the moving parts in internal combustion engines. It creates a film separating surfaces of adjacent moving parts to minimize direct contact, thereby decreasing heat caused by friction and reducing wear. Engine oil also has important cleaning and sealing functions, and serves as a medium for dissipating heat

throughout the engine. As a result, the Class Vehicles need the proper amount of engine oil for their engines and related parts to function properly and safely.

3. Modern automobile engines are not engineered to flow substantial quantities of oil into combustion chambers. When faulty engines permit more than *de minimus* amounts of oil to the combustion chamber, this leads to a host of serious problems, including prematurely low levels of engine oil, low oil pressure, lack of engine lubricity, engine knock, spark plug fouling and knock, and major damage to other critical engine parts, including, but not limited to, timing chains.

4. Prior to 2010, GM knew that the Class Vehicles contained one or more design and/or manufacturing defects, including, but not limited to, defects contained in the Class Vehicles' engines that cause them to be unable to properly manage the engine oil and, in fact, cause them to improperly burn off and/or consume abnormally high amounts of oil (the "Oil Consumption Defect").

5. The primary cause of the Oil Consumption Defect was the composition and construction of faulty piston rings, including both "compression" and "oil" rings. In particular, the composition of compression rings did not permit these rings to withstand the higher compression ratios of the LAF and LEA engines, in that the coating would fail and cause premature ring wear, and that these rings were too thin. Additionally, GM installed low-tension oil rings in these engines that do not maintain sufficient tension to keep oil in the crank case within design specifications. Individually or taken together, the EcoTec 2.4L piston rings failed to maintain a sufficient seal within the crankcase.

6. Included in the EcoTec 2.4L engine, which further contributes to the Oil Consumption Defect, are spray jets that spray oil onto the piston skirt and cylinder wall. This was not common in other engines with wider piston rings. This oil spray overloads and fouls the

defective piston rings, allowing oil to migrate past the piston rings into portions of the engine where this oil was not intended to go. This excess oil either burns off or accumulates as a carbon buildup on the combustion chamber's surfaces.

7. In addition, the EcoTec 2.4L engine includes a flawed Positive Crankcase Ventilation system that vacuums oil from the valve train into the intake system, where it is ultimately burned in the combustion chambers. This vacuuming process also contributes to excessive oil consumption.

8. The Class Vehicles incorporate a system that is supposed to warn drivers of low oil pressure caused by low engine oil levels. This system is referred to in this Complaint as the "Oil Pressure Warning" ("OPW") system. The OPW system is supposed to warn drivers of low levels of engine oil in two ways: First, the OPW system is supposed to display a textual warning on an alphanumeric display that GM calls the "Driver Information Center" ("DIC"), located in the dashboard in the instrument cluster immediately behind the steering wheel and in front of the driver. Second, the OPW is supposed to display an illuminated red image of an oil canister on the DIC. This illuminated warning light, called the "Engine Oil Pressure Light" in the Class Vehicles' manuals, signifies "that oil is not flowing through the engine properly" and that "[t]he vehicle could be low on oil."<sup>1</sup> As discussed in more detail below, the OPW's warnings do not provide any indication as to when the oil pressure in the Class Vehicles falls to levels low enough to damage internally lubricated parts or cause engine failure. Similarly, the Engine Oil Pressure Light illuminates well past the time when the Class Vehicles are below a critical oil level. Even if the

---

<sup>1</sup> GM, 2017 Equinox Owner's Manual 111.

Class Vehicles did adequately warn drivers of critically low oil conditions (which they do not), any such warnings would not prevent the damage caused by the Oil Consumption Defect.

9. Further contributing to the excessive oil loss and variety of engine damage problems caused by the Oil Consumption Defect in the Class Vehicles is GM's implementation of a defective oil life monitoring system. This system is referred to in this Complaint as the "Oil Life Monitoring" ("OLM") system. This system monitors engine conditions such as revolutions and temperature to estimate deterioration in oil quality and the remaining useful life of the engine oil following an oil change. After each oil change, the OLM system must be reset manually following each oil change. In each Class Vehicle, because the Oil Consumption Defect causes the engine oil to be consumed at an increased rate, the OLM system fails to advise drivers when insufficient oil remains in their vehicles. The OLM's function—to measure remaining oil life following an oil change based upon the regular estimated rate of oil consumption—is undermined by the Oil Consumption Defect, thereby rendering the OLM system useless. In fact, reliance on the OLM system instead encourages owners to drive with a false sense of security for thousands of miles after their oil levels fall dangerously low, because the OLM cannot display the correct remaining oil life based upon the increased defective oil consumption rate. Thus, the Class Vehicles provide no notice to drivers of the low oil levels who first learn of the problems when the vehicles stall or experience complete engine failures. The result is a system that causes drivers to travel thousands of miles with inadequate engine lubricity levels, wearing out and damaging moving internal engine components—a very serious problem in light of the Oil Consumption Defect causing excessive oil loss the Class Vehicles.

10. GM instituted a campaign in or about February 2013 to reprogram the OLM in Class Vehicles in order to reduce the recommended oil service intervals. On information and

belief, GM developed the new OLM program no later than December 2012. These changes were motivated by GM's recognition of the Oil Consumption Defect, to reduce expensive warranty repairs caused thereby. However, GM deliberately hid, and mislead, consumers about the true motivation for OLM reprogramming campaign. The OLM reprogramming campaign also reflects GM's recognition that owners of its vehicles rely on the OLM to guide them about when the engine oil in the Class Vehicles requires attention.

11. Problems associated with excessive oil consumption and the Oil Consumption Defect include, but are not limited to: unanticipated engine shutdowns, engine stalls, engines running excessively hot, spark plug fouling, engine misfires, unexpected loss of power, vehicle jerking, and other problems as discussed herein. Inadequate engine oil levels resulting from the Oil Consumption Defect have the potential to cause engine fires. The failure of the OPW and OLM systems to properly function and adequately warn the driver of the dangerously low oil levels amplifies the potential problems and dangers caused by the Oil Consumption Defect.

12. These problems create a substantial safety risk and therefore, the Class Vehicles do not provide for safe and reliable transportation.

13. The Oil Consumption Defect is a substantial safety concern because it causes excessive oil consumption that cannot be reasonably anticipated or predicted, and causes the engine to run while dangerously low on engine oil. The Oil Consumption Defect is unreasonably dangerous because it can cause engine failure while the Class Vehicles are in operation at any time and under any driving conditions or speeds, thereby placing drivers, passengers, and the public at risk of accidents and injury. In particular, the Oil Consumption Defect can result in:

- a. Sudden engine shutoff, resulting in loss of power, loss of braking, and inability to adequately maneuver in high-speed or congested driving situations;

- b. Driver distraction due to sudden and unexpected engine shutoff, caused by sudden loss of power, illumination of warning lights and sounds, and loss or diminution of power brake assist;
- c. Loss of maneuverability in high-speed or congested driving conditions due to unexpected loss of engine power—even when the engine does not shut off;
- d. Unexpected vehicle stalling when the vehicle comes to a stop in traffic, thereby endangering vehicle occupants by substantially increasing the risk that other vehicles will hit the Class Vehicles that have stalled unexpectedly; and
- e. Engine shutoff, failure (e.g., seizure), or stalling that strands vehicle occupants in remote, extreme, or unsafe locations or weather conditions.

14. The Oil Consumption Defect causes the Class Vehicles to consume unacceptably high amounts of engine oil. The rate of oil consumption for some Class Vehicles can exceed one quart of oil per 1,000 miles driven, or lower.

15. Plaintiffs and Class Members reasonably expected that their Class Vehicles would not experience excessive oil consumption during the vehicles' foreseeable and normal usage, including, but not limited to, the expectation that the Class Vehicles would not require unreasonably frequent oil changes/additions between regularly scheduled oil changes and that the Class Vehicles would not suffer from a dangerous defect that could cause the Class Vehicles to unexpectedly shut off, seize, stall, lose power, or catch fire during operation, creating the potential for accidents and injuries.

16. In particular, Plaintiffs and reasonable purchasers of an American manufactured four-cylinder vehicle such as the Class Vehicles reasonably do not expect their vehicles to consume more than one quart of oil between regularly scheduled oil changes. In this pleading,

“regularly scheduled oil changes” (or oil change interval, “OCI”) means the manufacturer’s recommended oil change interval.<sup>2</sup>

17. Prior to purchasing the Class Vehicles, Plaintiffs and Class Members did not know that the Class Vehicles suffered from the Oil Consumption Defect. GM did not disclose the Defect, nor did GM notify or instruct its authorized dealers to disclose the defect to Class Vehicle owners and prospective purchasers. Plaintiffs and Class Members therefore did not contemplate that the Class Vehicles’ engines would require supplemental oil to be added between regularly scheduled oil changes, as well as related repairs to address the defects costing hundreds to thousands of dollars.

18. GM knew and/or was on notice of, and was therefore reckless or deliberately indifferent in failing to conclude, that the Class Vehicles are defective and suffer from the Oil Consumption Defect and are not fit for their intended purpose of providing consumers with safe and reliable transportation.

19. As detailed in this pleading, GM actively concealed the Oil Consumption Defect from Plaintiffs and Class Members since the time they purchased or leased their Class Vehicles. GM’s concealment caused Plaintiffs and Class Members to experience the Oil Consumption Defect throughout the life of the Class Vehicles, including within the warranty period.

20. Had Plaintiffs and Class Members known at the time of purchase or lease about the Oil Consumption Defect and the associated costs and safety hazards related to the Defect, Plaintiffs and Class Members would not have purchased the Class Vehicles or would have paid less for them.

21. On information and belief, many owners of Class Vehicles suffer engine failure as a result of the Oil Consumption Defect. Many owners find after purchasing their Class Vehicles,

---

<sup>2</sup> GM recommends that Equinox owners “Check engine oil level and oil life percentage. Change engine oil and filter, if needed” every 7,500 miles. GM, 2017 Equinox Owner’s Manual 279.

resale value is greatly diminished, or nonexistent, due to the Oil Consumption Defect. For instance, Consumer Reports has listed the model year 2010 and model year 2011 Chevrolet Equinox and GMC Terrain as one of its “Used Cars To Avoid Buying” due to the engine problems associated with the Oil Consumption Defect.

22. Every Class Vehicle through model year 2015 was sold or leased pursuant to express and implied warranties, including a Powertrain Limited Warranty that covers the cost of all parts and labor necessary to replace or repair powertrain components, including the engine, pistons, and piston rings, that are defective in workmanship and materials within five years or 100,000 miles, whichever occurs first, calculated from the start date of the Basic Limited Warranty. GM reduced its powertrain warranty to five years or 60,000 miles, whichever occurs first, for model year 2016 and model year 2017. The Limited Warranty begins on the date in which the purchaser first put the vehicle into service. On information and belief, the Limited Warranty transfers automatically with the transfer of vehicle ownership during the warranty period.

23. GM has failed to recall the Class Vehicles to address the Oil Consumption Defect. GM has thus far failed to acknowledge that this Defect presents a substantial safety risk.

24. Beginning in August 2014 for the model year 2010 Class Vehicles, GM extended its Limited Powertrain Warranty to cover piston assemblies to ten years or 120,000, whichever occurs first, through a “Special Coverage Adjustment” (“SCA”). GM subsequently extended SCA coverage for model year 2011 and model year 2012 Class Vehicles to 7.5 years or 120,000 miles, whichever occurs first, through additional SCAs.

25. GM has not issued SCAs for the remaining Class Vehicles.

26. The SCAs are in all practical effect extended warranties.

27. Plaintiffs and Class Members who received Owner's Letters from GM pursuant to the SCAs, or were informed of the SCAs through an authorized GM dealer or other source, foreseeably relied upon GM's promise to repair engines and to replace other powertrain components relating to or damaged by the Oil Consumption Defect. Such reliance includes, but is not limited to:

- a. Not taking their vehicles into an authorized dealer for inspection or repair due to GM's instruction not to do so unless the OPW system warned of low engine oil pressure or levels;
- b. Relying on GM's OPW system to inform them of a possible engine oil problem, even though the OPW was faulty and did not reliably function to provide adequate warning; and

28. The Owner's Letters issued as part of the SCAs tells consumers that their vehicles "may" experience "excessive" oil consumption, but does not completely disclose the Oil Consumption Defect or its causes. Instead, on information and belief, the SCAs actively concealed the nature of the Defect, as detailed below.

29. The SCAs purported to impose unworkable and unreasonable preconditions on Plaintiffs and Class Members to obtain repair or replacement of their defective EcoTec 2.4L engines. Namely, the SCAs conditioned inspection and repair of Class Vehicles pursuant to the SCAs on the fact that the OPW system have previously warned owners of an issue with the engine oil in their Class Vehicle. These preconditions breached GM's warranty obligations.

30. Despite notice of the Oil Consumption Defect from various internal sources, GM has not recalled the Class Vehicles, has not offered all of its customers a suitable repair or replacement free of charge, has not replaced defective EcoTech 2.4L engines or authorized full

repair of all internal and external parts damaged by the Defect, and has not offered to reimburse all Class Vehicle owners and leaseholders who incurred costs related to the Defect, including, but not limited to, costs for inspections, diagnosis, repairs, and unreasonably frequent oil changes/additions between regularly scheduled oil changes.

31. As a result of their reliance on GM's omissions and/or affirmative misrepresentations, Plaintiffs and Class Members have suffered ascertainable losses of money, property, and/or of value of their Class Vehicles.

### **JURISDICTION AND VENUE**

32. This Court has jurisdiction over this action under the Class Action Fairness Act ("CAFA"), 28 U.S.C. § 1332(d). There are at least 100 members in the proposed class, the aggregated claims of the individual Class Members exceed the sum or value of \$5,000,000.00 exclusive of interest and costs, and Members of the Proposed Class are citizens of states different from Defendant.

33. This Court may exercise jurisdiction over GM because, through its business of distributing, selling, and leasing the Class Vehicles in this District, GM has established sufficient contacts in this District such that personal jurisdiction is appropriate.

34. Venues is proper in this District under 28 U.S.C. § 1391(a) because a substantial part of the events or omissions giving rise to Plaintiffs' claims occurred in this District. Specifically, Plaintiff Sanchez's Class Vehicle was purchased in this District.

### **PARTIES**

#### **Plaintiff Patrick Sanchez**

35. Plaintiff Patrick Sanchez is an Illinois citizen who lives in Palatine, Illinois. In February 2011, Mr. Sanchez purchased a new 2011 Chevrolet Equinox from Jennings Chevrolet

located in Glenview, Illinois. Prior to his purchase of the Class Vehicle, Plaintiff Sanchez read advertising about the Equinox and shopped around for the particular vehicle he would buy. Mr. Sanchez uses his vehicle for personal, family, or household purposes. His vehicle was designed, manufactured, sold, distributed, advertised, marketed, and warranted by GM. Mr. Sanchez's Class Vehicle came with a Basic New Limited Warranty and Powertrain Limited Warranty that accompanies all GM vehicles. Plaintiff Sanchez, a car enthusiast, purchased a third-party warranty at the time of his purchase from Premier Warranty Company to safeguard against problems not covered by the Basic New Limited Warranty or the Powertrain Limited Warranty.

36. Plaintiff Sanchez never learned of any oil consumption issues with the vehicles prior to the purchase of his Class Vehicle.

37. Upon information and belief, the oil level in Mr. Sanchez's vehicle was sufficient at the time of purchase.

38. Between 2011 and 2018, Plaintiff Sanchez performed normal and routine maintenance on her Class Vehicle either through an independent service technician or at Jennings Chevrolet.

39. In early 2012, Mr. Sanchez checked the oil level manually in his Class Vehicle and noticed it was low. Mr. Sanchez began manually checking the oil level in his Class Vehicle on a regular basis and noticed it was consuming more oil than he had experienced in other vehicles he previously owned.

40. Later in 2012, Mr. Sanchez took his Class Vehicle into a nearby Jiffy Lube where there was little to no oil found in his Class Vehicle when the service technician was trying to drain the oil from the Class Vehicle. From this point onwards, Plaintiff Sanchez made a habit of checking his oil when putting gas into his Class Vehicle. Almost every time Plaintiff Sanchez checked the

oil level in his Class Vehicle from late 2012 onwards, the dipstick was almost dry or considerably low despite recent oil changes.

41. Plaintiff Sanchez spoke with multiple service technicians about what the problem might be, including the service manager at Jennings Chevrolet. He was told either there was no issue or that this issue was typical for a car. Plaintiff Sanchez disagreed and inquired about having an oil consumption test performed, to which he was told that one could be performed the next time he brought his vehicle back. Following this interaction, which left Mr. Sanchez concerned, he started changing the oil in his Class Vehicle himself.

42. For the first time in early 2013, Mr. Sanchez heard a knocking noise coming from his Class Vehicle when the vehicle was idling. Although he was not aware of it at the time, as discussed herein this sound is called a “spark knock” meaning that internal damage had begun occurring within the engine of Mr. Sanchez’s Class Vehicle. This noise occurred continually during his use of his Class Vehicle from this point forward until his vehicle was repaired in January 2018.

43. Between 2013 and early 2018, Mr. Sanchez regularly checked his oil levels, often had to refill the oil due to the Oil Consumption Defect, and heard the knocking noise coming from his car. Mr. Sanchez has never had an Oil Level Low indicator nor Oil Pressure Low indicator illuminate in his Class Vehicle at any point during his ownership of his Class Vehicle.

44. Plaintiff Sanchez never received an SCA from GM. Plaintiff Sanchez reached out to GM and received a response; however, GM’s response did not include an offer to replace the defective engine in his Class Vehicle.

45. On January 6, 2018, with approximately 69,000 miles on the odometer, Plaintiff Sanchez was driving his vehicle when it shut off unexpectedly. Mr. Sanchez had checked the oil

only a few days before, and had added two quarts of oil to bring it back up to a normal oil level. At the time of the shutdown, he was able to safely pull off the road. He eventually was able to restart his Class Vehicle and drive home. His vehicle stalled out another three to four times on his way home. Specifically, Plaintiff Sanchez's vehicle would shut off completely while driving, then he would restart it. This pattern continued until he pulled into his own driveway.

46. After the shutdown incident, Mr. Sanchez had his Class Vehicle towed to Jennings Chevrolet for an inspection. He was told by service technicians that the engine within his Class Vehicle needed to be completely taken apart to diagnose the issue. Mr. Sanchez was quoted approximately \$3,000 for the repair to take apart his engine and replace his intake manifold. Ultimately, Mr. Sanchez was told the intake manifold within his Class Vehicle would not be covered by his Powertrain or Basic Limited Warranty. At the time, the vehicle had approximately 69,000 miles on the odometer.

47. Mr. Sanchez's third-party extended warranty covered \$2,342.34 of the repair; however, he paid \$436.85 out-of-pocket, including the \$60 to have his vehicle towed to Jennings Chevrolet from his driveway.

48. Mr. Sanchez's Class Vehicle currently has just over 70,000 miles on it. Plaintiff Sanchez is concerned that despite the repair, his Class Vehicle will continue to exhibit excessive Oil Consumption.

49. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Sanchez that his vehicle was experiencing the manifestation of the Oil Consumption Defect. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Sanchez that the Class Vehicle was low on oil at any point during his ownership of the Class Vehicle.

50. To date, Plaintiff Sanchez has regularly and routinely had the oil changed in his Class Vehicle. Since discovering the Oil Consumption Defect, Plaintiff Sanchez routinely checked his oil whenever he filled the vehicle with new gas.

51. Plaintiff Sanchez would not have purchased his Class Vehicle or would have paid less for it had he been aware of the Oil Consumption Defect, and had he known that the OPW system would not warn him if or when his Class Vehicle's engine was at risk. He did not receive the benefit of his bargain.

**Plaintiffs Mark and Sally Stauber**

52. Plaintiffs Mark and Sally Stauber ("the Staubers") are Illinois citizens who live in Glen Ellyn, Illinois. On March 4, 2011, the Staubers purchased a new 2011 Chevrolet Equinox from Sunrise Chevrolet located in Glendale Heights, Illinois. The Staubers use their vehicle for personal, family, or household purposes. Their vehicle was designed, manufactured, sold, distributed, advertised, marketed, and warranted by GM. The Staubers' Class Vehicle came with a Basic New Limited Warranty and Powertrain Limited Warranty that accompanies all GM vehicles.

53. Upon information and belief, the oil level in the Staubers' vehicle was sufficient at the time of purchase.

54. Between 2011 and 2017, the Stauber's performed normal and routine maintenance on their Class Vehicle either through an independent mechanic or at Jerry Haggerty Chevrolet.

55. In July 2013, the Staubers received a notice from GM that indicated their "balance chain pins may wear, allowing the chain to stretch." The notice indicated that this problem "would cause an engine noise, and if left untreated, could cause the chain to break, leading to engine damage." A true and complete copy of this letter is attached hereto as **Exhibit A**.

56. Upon information and belief, the balance chain pin wear and timing chain stretch result from their Class Vehicle having little to no oil within the Class Vehicle over an extended period of time. This is a common and resultant side effect of the Oil Consumption Defect.

57. In August 2017, the Staubers noticed the engine of their Class Vehicle was very loud when they started their vehicle. For the first time, the Staubers heard a knocking noise coming from their Class Vehicle when the vehicle was idling. At that time, the Staubers attempted to make an appointment with Jerry Haggerty Chevrolet in Glen Ellyn, Illinois. Although they described the problem they were having to the service department, they were informed that the first available appointment was a couple of weeks later. Having no other choice, they continued to drive their vehicle. They were not informed by the dealership that to continue to drive the vehicle would damage the engine.

58. On September 8, 2017, the Staubers were picking up a friend from a hospital in Naperville, Illinois, when their Class Vehicle would not start. They had their Class Vehicle towed to Jerry Haggerty Chevrolet for an inspection and repair. Upon inspection, the service technicians at Jerry Haggerty Chevrolet told the Staubers that they would have to take the engine apart to determine the cause of the engine failure. The service technicians were unable to start the vehicle themselves and informally quoted the Staubers \$600 to \$800 dollars for this engine inspection. The Staubers were also told that neither the inspection nor the repair would be covered under the Basic Limited Warranty or Powertrain Limited Warranty. Upon inspection, the technician inspecting the vehicle told the Staubers that the oil in their vehicle was 3.5 quarts low. The Stauber's vehicle has a 5 quart oil capacity, including the oil that remains in the oil filter

59. Although the Staubers were not aware of this information at the time, from the first time the Staubers heard a knocking noise coming from the engine of their vehicle when it was idling (called a “spark knock”), internal damage was occurring within the engine.

60. The OPW system in the Class Vehicle never displayed warnings to the Staubers that their vehicle was experiencing the manifestation of the Oil Consumption Defect. The OPW system in the Class Vehicle never displayed warnings to notify the Staubers that the Class Vehicle was low on oil at any point during their ownership of the Class Vehicle.

61. To date, the Staubers have regularly and routinely had the oil changed in her Class Vehicle. The Staubers regularly check the oil level in their Class Vehicle and have the oil changed in accordance with the vehicle’s specifications regularly and routinely.

62. To date, the Staubers’ Class Vehicle is inoperable. The vehicle has approximately 71,000 miles on it. It is being stored at Jerry Haggerty Chevrolet due to the Staubers having insufficient garage space to store the inoperable vehicle.

63. The Staubers would not have purchased their Class Vehicle or would have paid less for it had they been aware of the Oil Consumption Defect, and had they known that the OPW system would not warn them if or when their Class Vehicle’s engine was at risk. They did not receive the benefit of their bargain.

**Plaintiff Jacob Ross-Demmin**

64. Plaintiff Jacob Ross-Demmin is an Illinois citizen who lives in Washington, Illinois. In August 2013, Plaintiff Ross-Demmin purchased a new 2013 Chevrolet Equinox from Uftring Chevrolet located in Washington, Illinois. Plaintiff Ross-Demmin uses his vehicle for personal, family, or household purposes. His vehicle was designed, manufactured, sold, distributed, advertised, marketed, and warranted by GM. Plaintiff Ross-Demmin’s Class Vehicle

came with a Basic New Limited Warranty and Powertrain Limited Warranty that accompanies all GM vehicles.

65. Upon information and belief, the oil level in Plaintiff Ross-Demmin's vehicle was sufficient at the time of purchase.

66. Between 2013 and 2018, Plaintiff Ross-Demmin performed normal and routine maintenance on his Class Vehicle either through an independent mechanic or at Uftring Chevrolet.

67. In May 2017, Plaintiff Ross-Demmin's wife was driving on the interstate when his Class Vehicle shut off completely and unexpectedly. At the time of the shutdown, his wife was able to pull off the road. She eventually was able to restart the Class Vehicle after a few attempts and drive home. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Ross-Demmin's wife that the Class Vehicle was low on oil.

68. Immediately thereafter, Plaintiff Ross-Demmin took his vehicle to Uftring Chevrolet for an inspection. Upon inspection, service technicians at Uftring Chevrolet told Mr. Ross-Demmin they could not recreate the issues described and that his vehicle was "fine." Mr. Ross-Demmin was not quoted for any repairs by Uftring Chevrolet. The Oil Consumption Defect was not remedied by Uftring Chevrolet or disclosed to Plaintiff Ross-Demmin. Uftring Chevrolet then performed a routine oil change on the Class Vehicle. Uftring Chevrolet declined to tell Mr. Ross-Demmin whether his vehicle had any oil in it at the time of the inspection.

69. In approximately July 2017, Plaintiff Ross-Demmin's wife was driving with his young daughter in the car and his Class Vehicle again shut off unexpectedly. At the time of this shutdown, she was able to pull off the road. She eventually was able to restart the Class Vehicle and drive home. This stall greatly startled Plaintiff Ross-Demmin's wife. The OPW system in the

Class Vehicle never displayed warnings to notify Plaintiff Ross-Demmin's wife that the Class Vehicle was low on oil.

70. Again, immediately thereafter, Plaintiff Ross-Demmin took his vehicle to Uftring Chevrolet for an inspection. Upon inspection, service technicians at Uftring Chevrolet told Mr. Ross-Demmin they could not recreate the issues described and that his vehicle was "fine." Plaintiff Ross-Demmin was not quoted for any repairs by Uftring Chevrolet. The Oil Consumption Defect was not remedied by Uftring Chevrolet or disclosed to Plaintiff Ross-Demmin.

71. In August of 2017, Plaintiff Ross-Demmin noticed his Class Vehicle was idling strangely. Thereafter, he did some research and learned that multiple consumers were complaining of the Oil Consumption Defect with their Equinoxes. Thereafter, Plaintiff Ross-Demmin checked the oil manually in his Class Vehicle and noticed there was no oil on his dipstick. Thereafter, Plaintiff Ross-Demmin added oil manually to his Class Vehicle.

72. In October 2017, Plaintiff Ross-Demmin was sitting in his Class Vehicle in the driveway in his home, idling when his Class Vehicle shut off unexpectedly. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Ross-Demmin that the Class Vehicle was low on oil.

73. Again, immediately thereafter, Plaintiff Ross-Demmin took his vehicle to Uftring Chevrolet for an inspection. Service technicians at Uftring Chevrolet changed the oil in Plaintiff Ross-Demmin's Class Vehicle during this visit to the dealership.

74. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Ross-Demmin or his wife that their vehicle was experiencing the manifestation of the Oil Consumption Defect. The OPW system in the Class Vehicle never displayed warnings to notify

Plaintiff Ross-Demmin and his wife that the Class Vehicle was low on oil at any point during their ownership of the Class Vehicle.

75. To date, Plaintiff Ross-Demmin has regularly and routinely had the oil changed in his Class Vehicle in accordance with the manufacturer's suggested oil change intervals. Since discovering the Oil Consumption Defect, Plaintiff Ross-Demmin has begun checking the oil level in his Class Vehicle much more often and has had the oil changed more often between regularly scheduled oil changes: roughly every 1,500 miles.

76. Plaintiff Ross-Demmin would not have purchased his Class Vehicle or would have paid less for it had he been aware of the Oil Consumption Defect, and had he known that the OPW system would not warn him if or when his Class Vehicle's engine was at risk. He did not receive the benefit of his bargain.

**Plaintiff Jennifer Herrington**

77. Plaintiff Jennifer Herrington is an Illinois citizen who lives in Montgomery, Illinois. On February 21, 2015, Plaintiff Herrington purchased a used 2011 Chevrolet Equinox from Ron Westphal Chevrolet located in Aurora, Illinois with 53,000 miles on it. Prior to her purchase, Plaintiff Herrington and her husband researched vehicles that would be reliable and safe for their children. Plaintiff Herrington uses her vehicle for personal, family, or household purposes. Her vehicle was designed, manufactured, sold, distributed, advertised, marketed, and warranted by GM. Plaintiff Herrington's Class Vehicle came with a Basic New Limited Warranty and Powertrain Limited Warranty that accompanies all GM vehicles.

78. Upon information and belief, the oil level in Plaintiff Herrington's vehicle was sufficient at the time of purchase.

79. Between 2013 and 2018, Plaintiff Herrington performed normal and routine maintenance on her Class Vehicle through a professional service technician.

80. In August or September of 2017, Plaintiff Herrington attempted to accelerate from a stoplight in her Class Vehicle when her Class Vehicle sputtered and hesitated. Concerned, Plaintiff Herrington manually checked the oil within her Class Vehicle, finding that there was little to no oil in it. From that point onwards, Plaintiff Herrington made a habit of checking the oil within her Class Vehicle every three weeks.

81. Concerned about her vehicles sporadic sputtering, on December 22, 2017, Plaintiff Herrington took her vehicle to Ron Westphal Chevrolet for an inspection. Upon inspection, service technicians told Plaintiff Herrington that the timing chain within her Class Vehicle needed to be replaced. The service technicians did not explain why the timing chain needed to be replaced, and no repair or replacement of the timing chain was performed at that time.

82. In addition, although Plaintiff Herrington was not aware of this information at the time, from the first time the Plaintiff Herrington heard a knocking noise coming from the engine of her vehicle when it was idling (called a “spark knock”), internal damage was occurring within the engine.

On December 25, 2017, Christmas day, Plaintiff Herrington’s husband was driving the Class Vehicle on a rural street when it shut off unexpectedly and began to coast. Plaintiff Herrington’s husband was able to pull over to the side of the road and had the Class Vehicle towed to their residence. Plaintiff Herrington had approximately 83,000 miles on the vehicle at the time. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Herrington’s husband that the Class Vehicle was low on oil.

83. Shortly thereafter, Plaintiff Herrington had her vehicle towed to Petit Auto in Aurora Illinois for an inspection. Upon inspection, service technicians told Plaintiff Herrington that the timing chain within her Class Vehicle needed to be replaced in addition to other repairs that could not be determined since her Class Vehicle could not run. The service technicians did not explain why the timing chain needed to be replaced. Plaintiff Herrington was quoted \$2,100 for the repairs and was told neither her Basic New Limited Warranty nor Powertrain Limited Warranty would cover the cost of repair. No repair or replacement of the timing chain or other repairs were performed at that time.

84. On, February 20, 2018, Plaintiff Herrington took her Class Vehicle to Ron Westphal Chevrolet in Aurora, IL for further inspection and diagnosis. Upon inspection, service technicians determined that the entire engine needed to be replaced within her Class Vehicle. The service technicians did not explain why the entire engine needed to be replaced, instead only explaining that the engine was “bad” and needed to be fully replaced. Plaintiff Herrington was quoted \$7,357.35 for a complete engine replacement. A true and complete copy of this quote is attached hereto as **Exhibit B**. Representatives at Ron Westphal Chevrolet explained that Plaintiff Herrington’s warranties on her Class Vehicle had expired and that she would be responsible for the full cost of repairs. No repair or replacement of the engine was performed at that time, given the high costs quoted for the repair/replacement.

85. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Herrington or her husband that their vehicle was experiencing the manifestation of the Oil Consumption Defect. The OPW system in the Class Vehicle never displayed warnings to notify Plaintiff Herrington and her husband that the Class Vehicle was low on oil at any point during their ownership of the Class Vehicle.

86. To date, Plaintiff Herrington has regularly and routinely had the oil changed in her Class Vehicle. Since discovering the Oil Consumption Defect in August 2017, Plaintiff Herrington routinely checked her oil roughly every 3-4 weeks. As the Defect persisted, Plaintiff Herrington began checking the oil level in her Class Vehicle weekly.

87. To date, Plaintiff Herrington's Class Vehicle is inoperable at her home. Plaintiff Herrington would not have purchased her Class Vehicle or would have paid less for it had she been aware of the Oil Consumption Defect, and had she known that the OPW system would not warn her if or when her Class Vehicle's engine was at risk. She did not receive the benefit of her bargain.

**Defendant**

88. Defendant General Motors LLC ("GM") is a Delaware limited liability company with its principal place of business located at 300 Renaissance Center, Detroit, Michigan, and is a citizen of the States of Delaware and Michigan. The sole member and owner of General Motors LLC is General Motors Holding LLC. General Motors Holdings LLC is a Delaware limited liability company with its principal place of business in the State of Michigan.

89. GM, through its various entities, including Chevrolet, designs, manufactures, markets, distributes, and sells its vehicles in this District and multiple other locations in the United States and worldwide. GM and/or its agents designed, manufactured, and installed the GM engine systems in the Class Vehicles. GM also developed and disseminated the owner's manuals, warranty booklets, advertisements, and other promotional materials related to the Class Vehicles.

### **FACTUAL ALLEGATIONS**

90. For years, GM designed, manufactured, distributed, sold, and leased the Class Vehicles. It has sold, directly or indirectly, through its dealers and other retail outlets, thousands of Class Vehicles throughout the United States.

91. After receiving numerous and persistent complaints about the Oil Consumption Defect, in July 2012, GM published an article in GM TechLink regarding excessive oil consumption in the 2.4L EcoTec LAF engine (“July 2012 GM TechLink article.”). The article was titled “Excessive Oil Consumption.”<sup>3</sup> A true and complete copy of this July 2012 GM TechLink article is attached hereto as **Exhibit C**.

92. On information and belief, GM TechLink is a monthly periodical published by GM for its dealership technicians and service personnel that discusses, among other matters, repair procedures concerning GM vehicles.

93. The GM TechLink and TSBs referenced in this Complaint are not generally made available to the public. They are not widely available to consumers.

94. In the July 2012 GM TechLink article, GM acknowledges the existence of the defect to its dealer technicians and notes, “Excessive oil consumption may be noticed on some 2010 Equinox and Terrain models equipped with the 2.4 L engines.” The article further notes, “this condition not be evident until the vehicle has accumulated 20,000 miles or more.” The July 2012 GM TechLink article further states: “Upon inspection, excessive oil in the fresh air side of the PCV system due to excessive crankcase pressure and blow-by may be noted. In addition, all four spark plugs will have obvious/excessive oil deposits on them.”

---

<sup>3</sup> The relevant portion of the July 2012 GM TechLink article, attached hereto as **Exhibit C**, titled “Excessive Oil Consumption” appears at page 3 of the exhibit.

95. The July 2012 GM TechLink article indicates that excessive oil consumption can be verified by *either* the presence of obvious oil deposits on all four spark plugs, *or* an oil consumption test.

96. The July 2012 GM TechLink article indicates that in cases where the cylinder walls exhibited “zebra stripe” wear patterns associated with excessive oil consumption in the LAF engine, the technician was to “replace the engine . . . since this engine does not have serviceable cylinder liners like some of the other Ecotec engines.”

97. On information and belief, the July 2012 TechLink article reproduces verbatim information contained in a service bulletin (Technical Service Bulletin, or “TSB”) published by GM prior to July 2012.

98. Namely, as the consumer complaints below indicate, GM was aware, or should have been aware, that the Oil Consumption Defect was present in the Class Vehicles dating back to at least September 2009. This date pre-dates the sale of any Class Vehicle to any of the Class Representatives.

99. Thus, by September 2009, GM knew or should have known through sufficient product testing, consuming complaints, or other methods, that the Class Vehicles contained the Oil Consumption Defect and posed a safety hazard.

100. The Class Vehicles contain one or more defects in materials, components, construction or design, including, but not limited to, the Oil Consumption Defect, as described herein.

101. Insufficient oil causes Class vehicle engines to stall, to run hot, spark plugs to foul, engines to misfire, the vehicles to experience unexpected loss of power, jerking and other problems, posing enough of a safety risk such that the vehicles do not provide safe reliable

transportation. The drivers are left at risk of the Class Vehicle being stranded in hazardous traffic conditions, dangerous weather conditions and/or remote locations.

102. On information and belief, GM learned of the Oil Consumption Defect prior to 2010 through sources not currently available to Class Members, including, but not limited to: (1) pre-release testing data; (2) early consumer complaints about the Oil Consumption Defect to GM and its dealers about the Class Vehicles, as well as other earlier model year versions of such vehicles; (3) testing conducted in response to those complaints; and (4) aggregate data from GM dealers, including dealer repair orders and high warranty reimbursement rates that can cost up to several thousand dollars for each class vehicle.

103. GM's authorized dealers routinely provide maintenance service for Class Vehicles, including the MY 2010 and 2011 Equinoxes and Terrains. One of the most frequent services performed for new car owners is an oil change.

**A. All Class Vehicles are sold with the Oil Consumption Defect Which Is Present At The Point of Sale.**

**1. The Piston Rings in the Class Vehicles Lead to Oil Consumption and Engine Damage.**

104. All Class Vehicles have engines that incorporate improperly coated compression rings or Low-Tension Oil Rings and other potential defects that are inherently defective because these defects allow excessive and dangerous oil consumption, which leads to inadequate engine lubricity.

105. The compression rings are not properly coated or are not robust enough to withstand the greater pressures generated by the EcoTec 2.4L engine. This causes premature ring wear and

allows excessive oil flow into the combustion chamber from the crankcase. This leads to further engine damage, including engine knock.

106. The Low-Tension Oil Rings do not apply sufficient tension to prevent oil from being consumed in the combustion chamber, which in turn fouls spark plugs, and creates harmful carbon buildup in the pistons and cylinders.

107. The Oil Consumption Defect is a safety concern because it prevents the engine from maintaining the proper level of engine oil and causes voluminous oil consumption that cannot be reasonably anticipated or predicted.

108. The Oil Consumption Defect causes the Class Vehicles to consume unacceptably high, abnormal amounts of oil during normal and foreseeable usage, which requires Class Members to pay for unreasonably frequent oil changes and/or additions after very short driving distances, as well as costly engine repairs/replacements that can cost thousands of dollars in order to repair the defect.

109. GM provided owners substantially similar express limited warranties for model years 2010-2015, and substantially similar express limited warranties for model year 2016 and subsequent vehicles but with reduced mileage coverage for its powertrain warranties on those model years.

110. In or about February 2013, GM sent “Customer Satisfaction” letters to all MY 2010-2013 Class Vehicle owners informing them that “GM [has] recently introduced into production a software update for the life monitor system [which] will recommend more frequent oil changes to support engine durability and overall operating costs.” (“February 2013 OLM Campaign.”) Further, GM informed class vehicle owners that, “[a]t no-charge, your GM dealer will update your vehicle with these same improvements.”

111. On information and belief, the GM February 2013 OLM Campaign reduced the maximum oil change interval from over 10,000 miles to no more than 7,500 miles, and also caused the OLM system to instruct drivers to change their engine oil much more frequently.

112. A motivating purpose for the GM February 2013 OLM Campaign was to conceal the Oil Consumption Defect and to reduce the costly warranty engine replacements, piston assembly replacements, and other repairs related thereto. By reprogramming OLM systems in Plaintiff's and Class Member's vehicles, GM effectively transferred its warranty repair costs to its customers in the form of more frequent oil service fees and costs for engine oil and oil filters.

113. Upon information and belief GM instituted the February 2013 OLM Campaign in an attempt to delay the onset of the costly engine repairs that Class Members are substantially certain to experience as a result of the defect alleged herein. By reprogramming the OLM to recommend more frequent oil changes, upon information and belief, GM hoped that fewer owners would drive thousands of miles with extremely low engine oil levels. Thus, this reprogramming of the OLM, while did not eliminate the Oil Consumption Defect. Nor did this reprogramming prevent premature powertrain component wear and other engine damage due to the defect. This reprogramming was an attempt to mask the manifestations of the Oil Consumption Defect and place the financial burden on Plaintiffs and Class Members.

114. By failing to inform the owners of MY 2010-2013 vehicles with the 2.4L EcoTec engine of its excessive oil consumption problems, GM mislead consumers, engaged in half-truths, and exposed its customers to substantial safety risks.

115. In or about August 2013, GM published another article in TechLink (August 2013 TechLink article"), entitled "2.4L EcoTec Engine Oil Consumption." In this article, GM again acknowledges the existence of excessive oil consumption in certain Class Vehicles, claiming that

“Excessive oil consumption on some 2010-2013 LaCrosse, Equinox, Terrain and 2011-2013 Regal models equipped with the 2.4L engines does not require engine replacement. If excessive oil consumption is confirmed after an oil consumption test, new piston and rings should be installed.”

A true and complete copy of this August 2013 TechLink article is attached hereto as **Exhibit D**.

116. The August 2013 TechLink article identified a defect in the 2.4L EcoTec engine’s piston rings, stating in part:

**Piston Ring Coating.** The top compression ring in the new kit has a more robust coating on it that is designed not to wear as quickly as the original coating. Tests indicate that it wears about 4-5 times longer than the original coating.

If the top compression ring is worn, it will allow combustion pressure past it, which causes the oil control rings to be less effective and results in excessive oil consumption.

117. In or around September 2013, GM also acknowledged the existence of the oil consumption engine defect in a Technical Service Bulletin (“TSB”) that it only makes available to its dealers, not consumers. A true and complete copy of this September 2013 TSB is attached hereto as **Exhibit E**.

118. Although the September 2013 TSB recommended certain engine repairs (*e.g.*, replacement of the pistons and rings as described above) “under warranty,” Defendant arbitrarily and unfairly instructed its dealers not to perform the engine repairs identified in the TSB under warranty unless the consumer’s vehicle undergoes an oil consumption test that has to show the consumer’s vehicle is consuming more than 1 quart of oil per 2,000 miles of driving. Defendant continued to impose the arbitrary, unfair, and onerous oil consumption test as a precondition to honoring its warranty obligations in subsequent TSBs and to this day.

119. The GM-imposed oil consumption test is itself an unreliable test for excessive oil consumption. For instance, a given Class Vehicle may “pass” GM’s mandated oil consumption test and in the next few weeks consume more than 1 quart of oil in 2,000 miles.

120. GM knows that its oil consumption test is onerous to its customers, and unreliable. For example, on June 25, 2014, William Parenteau filed a complaint against GM in the United States District Court for the Central District of California, Case No. 2:14-cv-04961, in which he included detailed allegations of an oil consumption test performed by GM’s authorized dealer in on his 2010 Equinox 2.4L vehicle. After the dealer, Bot Stall Chevrolet in Mesa, California, informed Mr. Parenteau that his vehicle had consumed no oil over a two-month, approximately 2,000 test period, Mr. Parenteau returned to this dealer a month and approximately 1,000 miles later. At that time, the dealer determined that there was no oil showing on the dipstick. On information and belief, these facts demonstrate that Mr. Parenteau’s Equinox consumed over 1.25 quarts over a 1,000 mile period immediately after having been told his vehicle had “passed” the oil consumption test.

121. In May 2014 GM published an updated TSB relating to the Oil Consumption Defect. A true and complete copy of this May 2014 TSB is attached hereto as **Exhibit F**.

122. As a result of their reliance on Defendant’s omissions or misrepresentations, owners and lessees of the Class Vehicles, including Plaintiffs, have suffered ascertainable loss of money, property, or value of their Class Vehicles.

123. The Class Vehicles are equipped with a 2.4L EcoTec engine, have an oil capacity of 5 quarts, and contain one or more design, materials, and/or manufacturing defects that causes their engines to consume abnormally high amounts of oil.

124. In order for the engine to run effectively without causing engine damage, such as heat and friction wear, the pistons and cylinder walls must have a thin film of oil between the opposing metal surfaces. The oil reduces friction and heat, prevents surface scarring, and helps the moving components slide freely past each other.

125. To keep oil in the crankcase, and to prevent oil from traveling around the pistons and into the combustion chamber, pistons are fitted with compression and oil control rings (collectively, “piston rings”). These piston rings must withstand combustion pressures and hold combustion gases in the combustion chambers, keeping the gases out of the crankcase.

126. In the Class Vehicles, the piston rings that GM installed in the 2.4L Engines fail to achieve their intended purpose of keeping oil in the crankcase and out of the combustion chamber. Further, the rings fail to achieve their intended purpose of trapping combustion gases in the combustion chamber and out of the crankcase.

127. Specifically, the Class Vehicles’ piston rings do not maintain sufficient tension, relative to the cylinder walls, and fail to keep oil from seeping past, resulting in excessive oil consumption and causing the problems described *infra*.

128. First, in the Class Vehicles, oil travels around the piston rings and reaches the combustion chamber, where it is burned during the engines’ power stroke, thereby reducing the quantity of oil in the vehicle, reducing engine lubricity, and increasing the risk of correspondent engine damage.

129. Second, the defective piston rings allow for oil to constantly foul the spark plugs in the Class Vehicles. Spark plug electrodes, protrude into the combustion chamber and generate the ignition spark. Importantly, the electrodes must be dry and free of debris to fire properly. When

oil migrates into the combustion chamber in the Class Vehicles, the oil coats the spark plugs' electrodes and either diminishes or altogether disables their firing performance.

130. Third, the oil that passes around the rings in the Class Vehicles, that is not burned in the combustion chamber, gathers and hardens, creating carbon buildup. Due to the excessive carbon buildup in the combustion chamber and on top of the pistons, the Class Vehicles suffer from pre-ignition detonation, or "spark knock" as it is commonly called. Pre-ignition detonation disrupts the proper seating of the piston rings in their respective grooves, which causes them to wear out as they grind against the cylinder walls improperly. This results in the rings not sealing properly and thus allows for even more oil consumption. Pre-ignition detonation also vaporizes the cylinder wall oil film, pushing it past the rings and into the crankcase where it is vacuumed into the intake manifold via the Positive Crankcase Ventilation ("PCV") system.

131. The Oil Consumption Defect is a latent defect that existed at the point of sale when Plaintiffs and Class Members purchased their Class Vehicles.

132. Because of the Oil Consumption Defect, Plaintiffs and Class Members did not receive the full benefit of their bargain in purchasing their Class Vehicles.

133. Prior to the spring of 2014, and upon information in 2013, GM issued a technical service bulleting (TSB) number 13-06-01-003 relating to the Oil Consumption Defect for MY 2010-2013 Class Vehicles. In this TSB, GM acknowledges that it has received customer "comments" on excessive oil consumption, "and/or that they have to add oil between oil changes." This TSB was not distributed to consumers. In the TSB, GM directs dealer technicians to conduct an "oil consumption test," but first to verify that the vehicles computer (Electronic Control Module) has been re-programmed "to adjust the engine oil life monitor to a maximum of 7,500 miles."

134. Upon information and belief, in or about December 2012 GM re-calibrated the Class Vehicles' ECM software for the OLM to reduce the maximum regular oil change interval to 7,500 miles, from potentially up to twice that figure (15,000 miles). Upon information and belief, a motivating factor for this re-programming of the OLM (retroactive for MY 2010, 2011, 2012, and many 2013 Class Vehicles [and Plaintiffs' vehicles]) was to surreptitiously reduce GM's exposure to major powertrain warranty repairs related to the Oil Consumption Defect. In particular, on information and belief, GM unilaterally and without informing Plaintiffs and Class Members of its true reasons for doing so, GM recognized by no later than the fall of 2012 that the 2.4L EcoTech engines in Class Vehicles were experiencing premature timing chain wear. On information and belief, this premature timing chain wear resulted from and was a symptom of the Oil Consumption Defect.

135. Upon information and belief, prior to the OLM re-programming by GM of the Class Vehicles, the recommended oil change interval for normal use was between 7,500 and 12,500 miles. In other words, an average recommended oil service interval on the Class Vehicles, as designed, was approximately 10,000 miles and no less than 7,500 for normal use (e.g., not extreme service conditions), depending upon the factors taken into account by the OLM software.

136. Upon information and belief, the EcoTech 2.4L engines that are the subject of this Complaint were not designed to consume 1 quart per 2,000 miles, or 1 quart per 3,000 miles, or 1 quart per 4,000 miles, or 1 quart per 5,000 miles, or 1 quart per 6,000 miles, or one quart per 7,000 miles. At most, on information and belief, the EcoTech 2.4L engine was designed to consume no more than 1 quart per 8,000 miles under normal service—a figure one-fourth the level later designated unilaterally by GM in TSB 13-06-01-003 and the SCAs described *infra* as not “excessive,” e.g., normal.

137. Subject to further investigation, because Class Vehicles that consumed oil at a rate greater than 1 quart per 8,000 miles or so consume oil at a rate greater than they are designed to do, they are defective in their materials or workmanship, or are otherwise subject to repair or component replacement under GM's implied and express warranties.

138. The oil consumption test that GM mandated prior to authorizing any repair under the TSB 13-060-01-003 or the 2014-2017 SCAs discussed *infra* is not reasonably required as a precondition for coverage under any warranty or SCA, in that, inter alia:

- a. It requires a minimum of five appointments by customers to the GM dealership;
- b. It exposes Plaintiffs and Class Members to unreasonable safety risk and risk of serious potentially catastrophic engine or exhaust system damage during the 2,000 miles GM directs that the test be conducted, which can potentially last months;
- c. It is set up to discourage customers from completing it, given the inconvenience, disruption, and expenses involved;
- d. It is unreliable, in that the same engine can "fail" a test at one point in time and later "pass" the test, according to GM's authorized dealers; and
- e. GM's test ignores other far more reliable indicia of excessive oil consumption, including its dealers' own service records, reports by customers of consumption rates, and reports from a customer's independent mechanic. GM's warranties do not permit GM to ignore these other indications of defect as an excuse for refusing to repair or replace defective engines or pistons and piston rings.

139. In August 2014, GM offered to repair MY 2010 Class Vehicles experiencing excessive oil consumption, as defined by GM. This repair included, among other things,

installation of new pistons and new piston rings with improved combustion gas control and wear characteristics due to an upgraded coating on the compression rings, increasing the ring radial thickness and increasing the ring height, and by decreasing the ring end gaps. However, as discussed *infra*, this “Special Coverage Adjustment” (SCA) was inadequate and ineffective for Class Members and Plaintiffs.

140. In July 2015, GM offered a repair to the MY 2011 Class Vehicles that was similar in material respects to the MY 2010 SCA. However, as discussed *infra*, this SCA was ineffective for Class Members and Plaintiffs.

141. In 2017, GM offered a repair to MY 2012 Class Vehicles that was similar in material respects to the MY 2010 and MY 2011 SCA. However, as discussed *infra*, this SCA was ineffective for Class Member and Plaintiffs.

142. Although GM was aware that this was a known defect in the Class Vehicles, it did not recall the class vehicles nor did it send any notice of the need for this repair to consumers including the Plaintiffs and Class who owned Class Vehicles.

**2. The Spray Jets in the Class Vehicles Contributes to Oil Consumption and Engine Damage.**

143. Included in the 2.4L engines, which further contributes to the Oil Consumption Defect, are spray jets that spray oil onto the piston skirt and cylinder wall, which is not common on other engines with wider piston rings. This oil spray overloads and fouls the defective piston rings, triggering oil to migrate past the piston rings into other places in the engine.

In addition, the excessive oil spray collects on the piston ring surfaces forming carbon buildup. Carbon buildup on the piston rings interferes with the rings’ seating in their grooves, and thus interferes with the rings’ ability to seal out oil. Once the rings lose proper groove seating, they

become misaligned with the cylinder bores. Immediate and aggressive ring deterioration occurs as the fragile rings scrape against the harder steel cylinder bores at unintended angles.

**3. The PCV System in the Class Vehicles Contributes to Oil Consumption and Engine Damage.**

144. GM's PCV system, as installed in each of the Class Vehicles, contributes to oil consumption and engine damage by vacuuming oil from the valve train. This system is closed to the atmosphere in that everything that is internal into the intake system of the engine and crankcase remains in the PCV system.

145. The PCV system's intended purpose is to vent valve train gas pressures and recirculate that gas pressure into the intake manifold. The intake manifold distributes fresh air pulled through the intake filter, and recirculated air vented from the valve train, to the engines' combustion chambers. PCV systems are not intended to vacuum oil from the valve train.

146. In the Class Vehicles, however, the PCV system vacuums oil from the valve train and feeds it into the intake manifold runners and ultimately into the combustion chambers. By vacuuming oil from the valve train, the PCV system results in increased oil consumption, carbon buildup and the associated pre-ignition detonation, ring wear, ring failure, ring buildup, spark plug fouling, combustion chamber oil burn, low lubricity levels, internal component wear and component failure.

147. GM acknowledged that its PCV system contributed to oil consumption in TSB #13-06-01-003H: Excessive Oil Consumption – Perform Oil Consumption Test and/or Install Piston and Piston Ring Kit. Released (Feb 9, 2016). TSBS are only seen by dealerships and not consumers; therefore, the Class and the Plaintiffs were unaware of its existence. In that TSB, GM instructs dealers to “[t]he oil consumption may have clogged/reduced PCV flow. The PCV system

should be serviced. Clean any ice/sludge/water/carbon out of the PCV pipes/hoes, the PCV nipple on the cam cover, the PCV orifice between the #2 and #3 intake runners.”

**4. The Class Vehicles Do Not Include a Warning System that Protects Drivers From the Effects of the Oil Consumption Defect.**

148. In addition to the Oil Life Monitoring System (which does not monitor oil level), the Class Vehicles include an oil pressure gauge on the dash and an oil canister image that ostensibly would illuminate when a vehicle is low on oil. However, neither illuminates for low oil level.

149. The oil pressure gauge in the Class Vehicles fails provide any indication as to when a vehicle is dangerously low on oil. The oil pressure gauges in the Class Vehicles either have no indicator for low oil pressure, or they contain a single red hash mark (an indication of zero PSI). The oil pressure gauges fail to indicate dangerously low oil levels, but instead only illuminate when the vehicles have no oil pressure, which is far beyond the point at which a lack of oil and oil pressure will damage or destroy the Class Vehicle’s engine.

150. Upon information and belief, the Class Vehicles communicate no visible or audible warnings of destructive oil pressure levels before the engines are damaged, internally seize, or fail altogether. Because the Class Vehicles provide no warnings prior to engine seizure or failure, they put the Vehicle’s occupants and public safety at risk.

151. Even if the Class Vehicles did adequately warn drivers of dangerously low oil conditions (which they do not), any such warnings would do nothing to prevent the full scope of the harms caused by the Oil Consumption Defect. Because the Oil Consumption Defect results in oil migrating past the piston rings, it causes carbon buildup on the ring and cylinder surfaces and

fouls spark plugs, even if drivers diligently, and constantly, top-off their oil. Once the spark plugs foul, hazardous engine misfire and engine shutdown events are unavoidable.

152. The OLM system, installed in each of the Class Vehicles, exacerbates the oil loss and engine damage problems caused by the Oil Consumption Defect, because the customers foreseeably rely on the OLM for guidance about when to attend to their engine oil needs. In particular, because Plaintiffs and Class Members reasonably do not expect to have to add oil between oil changes, they do not think that they need to worry about oil levels until the OLM tells them that they are due for an oil change.

153. On information and belief, GM understands that its customers rely on the OLM for guidance as to when to attend to engine oil service needs, including checking engine oil levels. Indeed, one of the reasons that GM re-programmed the Class Vehicles' OLM software was to encourage customers to attend to their engine oil level, directly or indirectly (by having the oil changed) more often.

154. GM's placement of the engine oil dipstick at a position in the engine compartment that is difficult to see further encouraged customers to rely on the dash indicators for information on when to check or service their engine oil.

155. GM could easily have ameliorated this confusion but chose not to do so. For instance, instead of saying that the engine oil had "72% quality remaining," or something similar, GM could have programmed the OLM to display "Engine oil quality 72% remaining – check engine oil level," or used a comparable method to call the distinction between oil quality and oil level to the customer's attention.

**5. The Oil Consumption Defect in the Class Vehicles Causes Excessive Oil Loss, Which Can Lead to Engine Damage.**

156. The Oil Consumption Defect in the Class Vehicles results in excessive oil consumption, pre-ignition detonation, premature ring wear, premature ring fouling, premature ring failure, and spark plug fouling. It also results in inadequate engine lubricity, which creates increased friction, heat, metal on metal contact, and resulting premature engine damage. That means that each Class Vehicle has suffered, and will continue to suffer, internally lubricated component premature wear and failure.

157. The internal engine components that are subject to premature wear and failure include: pistons, cylinder walls, rings, valves, valve guides, valve stem seals, lifters, push rods, camshafts, rockers, bearings, piston rods, wrist pins, crankshafts, and timing chain components.

158. Due to the Oil Consumption Defect, all of the Class Vehicles have suffered and will continue to suffer excessive oil consumption, creating metal-on-metal friction, heat levels that far exceed GM's original specifications, and resulting premature engine damage and rapid destruction.

159. Excessive friction and heat expansion will accelerate wear of internal metal components, sending metal shavings into the crankcase. The shavings travel through the oil passages and frequently become lodged in tight spaces, where they cut into component surfaces moving against them and potentially blocking oil passages.

160. Once the internal components are scarred and/or worn, they cannot be repaired and must be replaced. The friction and heat expansion damage caused by the Oil Consumption Defect is irreversible.

**6. The Oil Consumption Defect Within the Class Vehicles Presents an Unreasonable Safety Risk.**

161. Without sufficient oil and lubricity, the engines in the Class Vehicles will overheat and potentially catch fire.

162. In its owners' manuals for the Class Vehicles, GM warns: "Oil levels above or below the acceptable operating range shown on the dipstick are harmful to the engine." Excessive oil consumption can cause engine oil levels to fall to a point where oil pressure is reduced. As GM expressly acknowledges in the Class Vehicles' owner's manuals, low oil pressure presents an engine fire risk, stating: "Do not keep driving if the oil pressure is low. The engine can become so hot that it catches fire. Someone could be burned.

163. Because the OPW system on Class Vehicles does not function properly to warn drivers of low oil pressure, the Oil Consumption Defect presents a direct risk of engine fires.

164. Low oil conditions are also unsafe because, if the engine experiences enough damage, the Class Vehicles' engines will seize and the Class Vehicles will shut down unexpectedly, which could cause an accident or leave drivers and passengers stranded in an unsafe situation. Upon information and belief, GM warns against this possibility in some of its automobile manuals, cautioning drivers that if a vehicle is driven while the engine oil pressure is low, severe engine damage may occur.

165. The Oil Consumption Defect also causes an unreasonable safety risk because excessive oil getting past the piston rings and fouling spark plugs causes engine misfires and engine shutdown that can leave drivers stranded and without the use of their vehicle. Further, the ignition failure caused by fouled spark plugs results in sluggish throttle response which places occupants in harm's way as they interact with other traffic. A Class Vehicle suffering from

weakened ignition function cannot accelerate as GM intended. A Class Vehicle suffering from total ignition failure will not even run. Both conditions place occupants in any number of hazardous conditions that would not exist but for the Oil Consumption Defect.

166. The knocking sound that emits from Class Vehicles is a result of the engine undergoing a “spark knock.” Unbeknownst to ordinary drivers, a knocking sound from their Class Vehicles’ engine means that complete engine shutdown or a stall could happen at any point throughout their trip. Oftentimes, just as with the Plaintiffs, drivers have no idea as to the cause and significance of the knocking noise made by their Class Vehicles during normal vehicle use.

167. As explained above, drivers are not protected from these safety risks by any timely warning from their Class Vehicles that their oil levels are getting low. Upon information and belief, the Class Vehicles do not provide any warning of low oil levels until the oil has already reached a level that is concurrent with engine misfire and shutdown and therefore unsafe.

#### **7. GM’s Knowledge and Refusal to Remedy the Oil Consumption Defect**

168. GM knew by no later than late 2009 that the Class Vehicles contained the latent Oil Consumption Defect from the time they left the factory.

169. Alternatively, GM did not adequately test the LAF and LEA piston rings prior to their utilization. Instead, GM recklessly introduced the use of inadequately coated faulty low-tension oil rings, that did not provide sufficient compression, without verification that they would not adversely impact engine safety and performance.

170. The Oil Consumption Defect was so prevalent in 2010 Chevrolet Equinox models that GM issued Service Bulletin, SB-13-06-01-003F (the “Service Bulletin”), attached hereto as **Exhibit F**, to aid repair technicians who encountered 2010 Class Vehicles with the Oil Consumption Defect.

171. Issued in May of 2014, the 2010 service bulletin, acknowledges “[s]ome customers may comment on excessive oil consumption and/or that they have to add oil between oil changes.”

(*Id.*)



## Service Bulletin

File in Section: 06 - Engine

Bulletin No.: 13-06-01-003F

Date: May, 2014

# TECHNICAL

**Subject:** Excessive Oil Consumption – Perform Oil Consumption Test and/or Install Piston and Piston Ring Kit

**Models:** 2010-2013 Buick LaCrosse  
2011-2013 Buick Regal  
2012-2013 Buick Verano  
2010-2013 Chevrolet Equinox  
2012-2013 Chevrolet Captiva, Orlando (Canada Only)  
2010-2013 GMC Terrain  
Equipped with 2.4L Engine (RPOs LAF, LEA)

This bulletin has been revised to update the Parts Information. Please discard Corporate Bulletin Number 13-06-01-003E.

**Condition**

Some customers may comment on excessive oil consumption and/or that they have to add oil between oil changes.

**Correction**

For this condition, technicians should perform an oil consumption test by following the latest version of Corporate Bulletin Number 01-06-01-011. Before starting the oil consumption test, verify the ECM has latest TIS2web calibrations to adjust the engine oil life monitor to a maximum of 7,500 miles (12,070 km) — Refer to the latest version of Customer Satisfaction Bulletin #12312.

Inspect for any obvious oil leaks that may explain the oil consumption concern and repair as necessary.

**Important:** When checking the oil level with the oil dipstick design shown below, please note that the oil volume per notch is not linear due to the shape of the block. The upper notches (relative to the top of the handle) equal 0.24 quart (0.227 L) between each notch while the lower notches only equal 0.14 quart (0.132 L) between each notch. As a result, no oil will appear on the dipstick if it is low on oil by approximately 1.25 quarts (1.18 L) or more. When determining the oil consumption rate, the oil volume added to return it to the starting location is the total amount of oil consumed. The consumption rate must be documented on a repair order.


**Notice:** Do not add too much oil. An overfill can lead to burn off of the excess oil. Advise the customer to wait until the oil is below the cross-hatched area at the tip of the dipstick before adding oil.



If the oil consumption test indicates that the rate of consumption is greater than 1 quart (0.946 L) of oil every 2,000 miles (3,200 km), note the oil consumption rate, the date that the ECM was reprogrammed and any repairs/diagnosis that you have performed.



- Camshafts and roller follower will have wear markings. This is normal and do not need to be replaced (refer to picture above).



- Valves stems may have deposits build up on them. These deposits are characteristic of a direct inject engine. The valves stems do not need to be cleaned as they are not affecting engine performance (Refer to picture above).

**Parts Information**

Part Number	Description
19303450	PISTON AND RING KIT, ENG (Set of 4)
12637166	GASKET KIT, CYL HD
12609291	SEAL, CM/SHF

**Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4080008*	Oil Consumption Test Setup	0.2 hr
4080178*	Piston, Connecting Rod and Bearing Replacement (Includes Oil Consumption Test)	9.5 hrs
Add	To Replace Fuel Pump (2010-2011 Models Built Prior to March 2011 Only)	0.7 hr
Add	To Replace Balance Shaft Chain and Tensioner (2010-2011 Models Built Prior to March 2011 Only)	0.8 hr
Add	To Replace Timing Chain (2010-2011 Models Built Prior to March 2011 Only)	0.5 hr

\*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.

172. In addition to the Service Bulletin that was only distributed to authorized GM dealerships, GM sent out a SCAs for Model years 2010, 2011, 2012 to a few owners. Many, did not even receive the SCA or know of its existence. An actual version of a MY 2012 SCA is pictured below.

May 2017

This notice applies to your vehicle, **VIN:**

Dear

As the owner of a 2012 model year Chevrolet Equinox, your satisfaction with our product is very important to us.

This letter is intended to make you aware that some 2012 model year Chevrolet Equinox vehicles, equipped with a 2.4L engine, may exhibit excessive engine oil consumption (less than 2,000 miles per quart of engine oil), due to piston ring wear. If this condition is present, an audible rattle or knock from the engine may be heard. The engine oil pressure telltale may illuminate on the instrument panel or the following message may appear in the Driver Information Center: "Oil Pressure Low – Stop Engine."

**Do not take your vehicle to your Chevrolet dealer as a result of this letter unless you believe that your vehicle has the condition as described above.**

**What We Have Done:** General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your 2012 Chevrolet Equinox within 7 years and 6 months of the date your vehicle was originally placed in service or 120,000 miles, whichever occurs first, the condition will be repaired for you at **no charge**. Diagnosis or repair for conditions other than the condition described above is not covered under this special coverage program.

**What You Should Do:** It is a good idea to check the engine oil level at each fuel fill. Your vehicle owner manual has instructions on checking engine oil in the Vehicle Care section. If you believe that your vehicle has the condition described above, repairs and adjustments qualifying under this special coverage must be performed by a Chevrolet dealer. You may want to contact your Chevrolet dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

**Reimbursement:** If you have paid for repairs for the condition described in this letter, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by May 31, 2018, unless state law specifies a longer reimbursement period.



173. Further, in order to receive a fix pursuant to the SCA, GM requires that an oil consumption test be conducted to determine if a full replacement of pistons and rings is required.

Specifically, GM notes:

- If the oil consumption test indicates that the rate of consumption is less than 1 quart (0.946L) of oil every 2,000 miles (3,200 km), note the oil consumption rate and the date that the ECM was reprogrammed. No further action is required.
- If the oil consumption test indicates that the rate of consumption is greater than 1 quart (0.946 L) of oil every 2,000 miles (3,200 km), note the oil consumption rate, date that the ECM was reprogrammed and replace the pistons and rings.

174. Many of the consumers who received notice SCA from GM did not receive the piston ring repair. Namely, despite a Class Member's Class Vehicle exhibiting excessive oil consumption, often dealerships tell the Class Members their Class Vehicles have not exhibited sufficient oil consumption to receive the fix under the GM's TSB or its SCAs. Upon information and belief, thousands of customers have been denied piston ring replacements pursuant to the terms of the TSB and SCAs and others never received notice of the defect or its eligibility for coverage at all.

175. GM had knowledge of an excessive and dangerous oil consumption issue during the class period due to the faulty LAF and LEA piston rings and related defects in the engine. The excessive oil consumption indicates that there is a severe and latent defect with the engine that would have been demonstrated had GM performed adequate testing.

176. GM had and continues to have a duty to disclose the Oil Consumption Defect and the associated out-of-pocket repair costs to Plaintiffs and Class Members because: (1) the defect poses an unreasonable safety hazard; (2) GM had and continues to have exclusive knowledge and/or access to material facts about the Class Vehicles and engines that is not reasonably discoverable by Plaintiffs and Class Members; (3) GM has actively and fraudulently concealed the defect from its customers despite its knowledge, and (4) GM has communicated half-truths to customers, directly through owner letters and indirectly through its dealer network, regarding the nature of the Oil Consumption Defect.

**B. Customers Repeatedly Complained About Excessive Oil Consumption and Engine Damage in the Class Vehicles and Earlier Models.**

177. As shown below, excessive oil loss, ticking or knocking noises coming from the engines, and stalling have been common complaints among drivers Class Vehicles. During the class period there was an unusually large number of complaints of excessive oil consumption such that GM was put on notice of a specific problem.

178. On information and belief, GM began its design and manufacture of the 2.4L EcoTec engine under the “Old GM,” i.e., the GM that filed bankruptcy and was ultimately reconstituted into “New GM” in 2009. As recognized by the Second Circuit, when Old GM declared bankruptcy, Defendant (New GM) immediately took over its business, without any “reorganization” as traditionally takes place in the case of a bankruptcy. *Elliot v. GM LLC*, 829 F.3d 135, 145-46 (2d Cir. 2016). Knowledge derived from complaints received by Old GM can be imputed to Defendant GM, at least insofar as that knowledge was in the possession of Old GM employees who continued employment at New GM or the knowledge was contained in a file transferred from Old GM to New GM. *See In re Motors Liquidation Co.*, 541 B.R. 104, 108 (Bankr.

S.D.N.Y. 2015). Thus, upon information and belief, Defendant GM, at its inception, like Old GM, had knowledge of the Oil Consumption Defect relating to the EcoTec 2.4L engineering, research, and testing.

179. Upon information and belief, faced with the fact that Class Vehicles were suffering excessive oil and engine damage due to the Oil Consumption Defect, GM issued multiple Technical Service Bulletins addressing the oil consumption issue (“TSBs”). But it did not recall all models affected by the Oil Consumption Defect. The TSBs suggested fixes to address symptoms and problems caused by or related to the Oil Consumption Defect, but GM eventually acknowledged *in* TSB 13-06-01-003 that the minimum necessary repair or component part replacement necessary to address this defect involved replacing the piston assemblies, including both pistons and piston rings.<sup>4</sup> Upon information and belief, the latest version of these TSBs was released on February 9, 2016.

180. Despite this knowledge, GM took no proactive steps like a recall to remedy this defect before damage was done to the engines, knowingly leaving Plaintiffs and the other Class Members driving defective Class Vehicles.

181. Upon information and belief, thousands of purchasers and lessees of the Class Vehicles have experienced manifestations of the Oil Consumption Defect. Complaints filed by consumers with the NHTSA and posted on various internet sites (e.g, terrainforum.com; carcomplaints.com, etc.) demonstrate that the Oil Consumption Defect is widespread.

182. GM, like other automobile manufacturers, monitors NHTSA and other complaints as part of its quality control measures. These complaints, some of which are included below, show

---

<sup>4</sup> See TSB #13-06-01-003H: Excessive Oil Consumption – Perform Oil Consumption Test and/or Install Piston and Piston Ring Kit. Released (Feb 9, 2016).

GM's awareness of the Oil Consumption Defect and its potential danger (note that spelling and grammar mistakes remain as found in the original):

- NHTSA Complaint on July 28, 2017 for 2010 Chevrolet Equinox:  
“TL\* THE CONTACT OWNS A 2010 CHEVROLET EQUINOX. WHILE DRIVING 5 MPH PULLING INTO A SERVICE STATION, THE VEHICLE STARTED TO JERK VIOLENTLY. THE CONTACT SHIFTED THE GEAR INTO PARK. WHEN SHE ATTEMPTED TO SHIFT THE GEAR INTO REVERSE, THE GEAR SHIFTER FAILED TO GO INTO REVERSE. THE ENGINE WARNING INDICATOR ILLUMINATED WITH FAILURE CODE: P0776. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC (FISHER TRANSMISSION) WHERE IT WAS DIAGNOSED THAT THE PISTON RING, SNAP RING, AND 3-5R WAVE PLATE WERE DETACHED WITH METAL SHELVING AND NEEDED TO BE REPLACED. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS CONTACTED AND INFORMED THE CONTACT THAT THE VEHICLE WAS NOT COVERED UNDER THE WARRANTY. THE MANUFACTURER DID NOT OFFER FURTHER ASSISTANCE. THE APPROXIMATE FAILURE MILEAGE WAS 113,000. UPDATED 11/07/17\*LJ”
- NHTSA Complaint on July 8, 2017 for 2010 Chevrolet Equinox:  
“PURCHASED VEHICLE USED IN 2013 WITH 28K MILES. STARTED NOTICING AN ENGINE KNOCK IN 2016, IN BETWEEN OIL CHANGES, @ APPRX. 85K MILES. BEGAN HAVING TO ADD 3-4 QUARTS OF OIL EVERY 1000 MILES, GIVE OR TAKE. CALLED DEALERSHIP FOR SERVICE - WHILE WARRANTY WAS STILL IN EFFECT - AND WAS TOLD IT WAS A COMMON PROBLEM WITH THIS ENGINE, AND ADDING OIL WAS ALL THAT NEEDED TO BE DONE. WHILE DEALING WITH THAT, HAD TO REPLACE THE SENSOR, AS VEHICLE STALLED WHILE IN A LEFT TURN LANE, WHICH ALMOST CAUSED ME TO BE REAR ENDED. DECEMBER 2016 - OIL CONTINUED TO BE BURNED AT AN ALARMING RATE, SO MY HUSBAND CONTACTED A FRIEND WHO WORKS FOR A CHEVY DEALER. WE WERE TOLD NOT ONLY IS THE MASSIVE OIL CONSUMPTION NOT NORMAL, BUT THAT GM IS FULLY AWARE OF THE PROBLEM, BUT REFUSING TO ISSUE A RECALL OR PAY TO HAVE THE PISTONS REPLACED! 2017 - HAVE CONTINUED TO ADD 2-4 QUARTS OF OIL EVERY 1000 MILES OR SO; THEN MAY 2017,

RECEIVED NOTICE FROM GM ACKNOWLEDGING THE PISTON RING WEAR/EXCESSIVE OIL CONSUMPTION, BUT THAT IT'S ONLY REPAIRABLE WITHIN 7 YEARS 6 MONTHS OF ORIGINAL IN-SERVICE DATE, OR 120,000 MILES, WHICHEVER COMES FIRST! SERIOUSLY?! I AM PAST BOTH & AM PISSED OFF! GM HAS KNOWN ABOUT THIS PROBLEM FOR YEARS, AND NEEDS TO TAKE FULL RESPONSIBILITY, NOT IMPOSE A YEAR/MILEAGE CAP! I WONDER IF A CLASS-ACTION LAWSUIT WOULD WAKE THEM UP? I'M NOT OPPOSED TO LOOKING INTO IT! DON'T GET ME WRONG - PREVIOUS TO MY EQUINOX, I OWNED AN HHR FOR 11 YEARS, AND PRIOR TO THAT, A SUBURBAN FOR 5 YEARS. I LIKE MY CHEVY'S BUT THIS ISSUE HAS LEFT A BAD TASTE FOR THEM, AND AM TOTALLY UNIMPRESSED WITH THEIR LACK OF CONCERN REGARDING THIS ISSUE. FOR THOSE OF US THAT ARE PAST THE VERY CONVENIENT YEARS/MILES, THIS IS A VERY EXPENSIVE OUT OF POCKET REPAIR. I CAN'T EVEN TRADE IT IN, AS I STILL OWE ON THE DAMN LOAN!! STEP UP GM, & DO THE RIGHT THING! BY THE WAY - HUBBY IS REPLACING THE TIMING CHAIN TODAY :O[“

- NHTSA Complaint on July 8, 2017 for 2010 Equinox: “WAS TOLD BY MY MECHANIC THE VEHICLE WAS BURNING OIL. FOUND OUT IN MAY 2017 THAT CHEVY IS AWARE OF A DEFECTIVE PISTON RING PROBLEM THAT CAUSES THIS. THEY HAVE BEEN AWARE SINCE AT LEAST 2015. WAITED 2 YEARS TO NOTIFY ME BY MAIL. WHEN I WENT TO A DEALER TO HAVE PROBLEM FIXED I WAS TOLD VEHICLE HAS TOO MANY MILES ON IT. IT WOULD NOT HAVE HAD TOO MANY MILES HAD I BENN NOTIFIED 2 YEARS AGO!”
- NHTSA Complaint on October 15, 2017 for 2012 Chevrolet Equinox: “TL\* THE CONTACT OWNS A 2012 CHEVROLET EQUINOX. WHILE DRIVING VARIOUS SPEEDS, A KNOCKING NOISE WAS HEARD COMING FROM THE ENGINE WITHOUT WARNING. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC WHO DIAGNOSED THAT THERE WAS A FAILURE WITH THE PISTON RING, WHICH CAUSED EXCESSIVE OIL CONSUMPTION. THE VEHICLE WAS NOT REPAIRED. THE CONTACT RECEIVED AN EXTENDED WARRANTY NOTIFICATION FOR THE ENGINE. THE MANUFACTURER STATED THAT THE VEHICLE WAS NOT COVERED UNDER THE EXTENDED WARRANTY DUE TO

EXCESSIVE MILEAGE. THE FAILURE MILEAGE WAS APPROXIMATELY 115,000."

- NHTSA Complaint on February 3, 2017 for 2012 Chevrolet Equinox: "I PURCHASED THIS PRE-OWNED EQUINOX SEPTEMBER 30. IN DECEMBER I FOUND OUT FROM MY MECHANIC THAT THERE IS AN OIL CONSUMPTION PROBLEM. IT'S NOT LEAKING OIL, IT'S USING OIL. HE PRINTED OUT DOCUMENTATION THAT SHOWS 2012 EQUINOX VEHICLES HAVE THIS OIL CONSUMPTION PROBLEM DUE TO FAULTY PISTON AND PISTON RING INSTALLATION. I BROUGHT IT TO MY LOCAL GMC/CHEVY DEALER AND HE SAID THERE IS NOTHING THAT GMC WILL DO FOR ME AND THAT IT WOULD BE \$3,000 TO FIX. I ASKED FOR AN OIL CONSUMPTION TEST BUT HE DIDN'T FOLLOW THROUGH TO SCHEDULE IT. THE VEHICLE HAD A POWER TRAIN WARRANTY THAT EXPIRED THIS LAST OCTOBER. BECAUSE OF THAT IT WON'T BE REPAIRED AT NO COST TO ME. BECAUSE THIS IS A KNOWN ISSUE THAT THIS VEHICLE ENGINE WAS PUT TOGETHER INCORRECTLY, THERE IS NO WAY THAT I SHOULD PAY FOR THE REPAIR. OVER TIME THIS WILL CAUSE IRREPARABLE DAMAGE TO THE ENGINE, LEAVING ME WITH MULTIPLE EXPENSIVE UPKEEP AND THE INABILITY TO SELL. IT JUST TURNED TO 82,000 MILES. MY FIRST AMERICAN BOUGHT CAR AFTER OWNING FOREIGN CARS FOR DECADES. WANTED TO BE PATRIOTIC. I WON'T HAVE THAT MISJUDGMENT AGAIN. I FELT STUCK AT FIRST BUT THEN REALIZED THAT THIS IS NOT AN ACCEPTABLE CONCLUSION. GMC NEEDS TO STAND BEHIND WHAT THEY HAVE BUILT."
- NHTSA Complaint on February 11, 2017 for 2010 Chevrolet Equinox-"THE VEHICLE WAS IN MOTION, ACCELERATING ON A FREEWAY ENTRANCE RAMP. AS I WAS MERGING, THE ENGINE LOST POWER AND STARTED A LOUD KNOCKING NOISE. I COULD NOT ACCELERATE, STARTED SLOWING, BUT WAS ABLE TO GET TO THE SHOULDER. I HAD THE VEHICLE TOWED TO THE NEAREST CHEVY DEALER, WHERE A QUICK DIAGNOSIS WAS THAT THE ENGINE HAD FAILED, AND WOULD HAVE TO BE REPLACED. THIS ENGINE HAS HAD 2 WARRANTY REPAIRS RELATED TO OIL ISSUES (8/2011 AND 8/2014). IN BOTH CASES THE TIMING CHAINS, TENSIONER, GASKETS AND SEALS, ETC. WERE REPLACED. ALSO, IN 2014 THERE WAS A

RECALL TO REPROGRAM THE OIL LIFE MONITOR. THERE WAS A RECALL LETTER IN SEPTEMBER, 2014 REGARDING EXCESSIVE ENGINE OIL USE DUE TO PISTON RING WEAR CAUSED BY THE PREVIOUS ISSUES. THIS CONDITION WAS TO HAVE AN EXTENDED WARRANTY OF 10 YEARS OR 120,000 MILES. I BLAME THE ENGINE FAILURE AS AN EXTENSION OF THESE OIL RELATED ISSUES, WHILE CHEVY SAYS "NO".

- NHTSA Complaint on October 10, 2017 for 2010 Chevrolet Equinox:  
“GM IS AWARE OF AN OIL CONSUMPTION ISSUE ON 2010MY+ CHEVY EQUINOX AND GMC TERRAIN WITH THE 2.4L ECOTEC ENGINE. THEY HAVE SO FAR ISSUED SERVICE BULLETINS FOR 2010-2012MY TO REPLACE THE PISTON RINGS AND TIMING CHAIN BECAUSE IN THIS SITUATION, THE TIMING CHAIN CAN STRETCH CAUSING IT TO SKIP SEVERAL TEETH AND CAUSE ENGINE DAMAGE. I COMPLAINED ABOUT EXCESSIVE OIL CONSUMPTION (1 QUART EVERY ~1000 MILES) TO THE DEALER. THE DEALER IS INSTRUCTED TO DO AN OIL CONSUMPTION TEST BY GM. 200 MILES AFTER WE BEGAN THIS OIL CONSUMPTION TEST, I STARTED THE CAR ONE MORNING AND THERE WERE LOUD SOUNDS COMING FROM THE ENGINE COMPARTMENT. I CALLED FOR A TOW TO THE DEALER AND THEY SAID THE ENGINE WAS SEVERELY DAMAGED AND A NEW ENGINE IS RECOMMENDED. GM DOESN'T WANT TO TAKE OWNERSHIP FOR THIS KNOWN ISSUE. BULLETIN SB-10058791-5041”
- NHTSA Complaint on October 10, 2017 for 2013 Chevrolet Equinox:  
“THE ENGINE OF MY CHEVROLET EQUINOX HAS BEEN BURNING OFF WAY TOO MUCH OIL. I HAVE SEEN ONLINE THAT THIS IS AN ISSUE WITH MANY EQUINOXS. AFTER TAKING IT INTO THE DEALERSHIP, I WAS TOLD THAT THE PISTON RINGS ARE NOT SEALING, AND THUS LETTING MORE OIL THROUGH TO BE BURNED. THE ESTIMATED COST FOR REPAIR IS 3300 DOLLARS. CONSIDERING IT IS AN ENGINE FAILURE, GM SHOULD BE ON THE LINE FOR THAT COST. IT IS ALSO DANGEROUS, AS NO CHECK ENGINE LIGHT CAME ON WHEN MY OIL WAS DRAMATICALLY LOW LONG BEFORE I WAS DUE FOR AN OIL CHANGE. OVERALL A DANGEROUS FACTOR.”

- NHTSA Complaint on September 12, 2017 for 2011 Chevrolet Equinox: “#43180: VOLUNTARY PRODUCT EMISSION RECALL – HIGH PRESSURE FUEL PUMP – (SEP 30, 2016) CAR STALLS AFTER IDLING WHEN PULLING OUT OF PARKING LOT OR IN A SLOW START UP OR TRANSITIONING FROM REVERSE TO DRIVE. CAUSING THE VEHICLE TO LOSE POWER AND MANEUVERABILITY. THE ENGINE MOUNTED HIGH PRESSURE FUEL PUMP IN THESE VEHICLES MAY DEVELOP EXCESSIVE WEAR ON THE PLUNGER PISTON SHAFT AND SHAFT SEAL. IF THIS HAPPENS FUEL CAN LEAK INTO THE ENGINE OIL CRANKCASE AND RESULT IN THE ENGINE RUNNING ROUGH AND ILLUMINATION OF THE MALFUNCTION INDICATOR LAMP. THE ISSUE HAS BEEN ONGOING FOR PAST SEVERAL YEARS.”
- NHTSA Complaint on May 15, 2015 for 2013 Chevrolet Equinox: “THE ENGINE BURNS ABOUT A QUART OF OIL PER 1000 MILES. WE HAD A DEALER LOOK INTO IT, INCLUDING A DIP TEST EVERY 500 MILES. THEY FOUND THAT IT IS INDEED BURNING OIL, AND SAID DUE TO LOW TENSION RINGS AND SHORT SKIRT PISTON, THIS WAS NORMAL. I'M NO MECHANIC, BUT 3 QUARTS OF OIL PER NORMAL OIL CHANGE INTERVALS SEEMS REALLY EXCESSIVE. IT'S BEEN LIKE THIS PRETTY MUCH SINCE WE BOUGHT IT NEW. I GUESS IT COULD BE SAFETY RELATED BECAUSE SEVERE OIL CONSUMPTION COULD CAUSE A FIRE.”
- NHTSA Complaint on August 15, 2017 for 2011 Chevrolet Equinox: “DEALER LOOKED AT IT, IT USES OIL THEY SAY THERE IS AN ISSUE WITH STRETCHED TIMING CHAINS AND PISTON RINGS, WHICH COMPANY HAS ADMITTED THERE IS A PROBLEM WITH. BRANDED TITLE IS STOPPING THE FIXING OF PROBLEM. ONLY ISSUE TO MAKE TITLE BRANDED WAS BUMPER AND AC UNIT ISSUES(HAD TO DO WITH THE INSURANCE COMPANY IN THE STATE IT HAPPENED IN). THERE WASN'T ANY DAMAGE TO ENGINE / MOTOR. GM WILL NOT STAND BEHIND THERE PRODUCT LIKE THEY CLAIM. THEY ALREADY ISSUED THIS POLICY #15285, THEY SHOULD HONOR THE FIX!! - REGARDLESS! VEHICLE IS 2011 WITH ONLY 67,000 MILES. CALLED GM CUS. SUPPORT, AS TOLD BY DEALER,THEY COULDN'T HELP. REPORT # 8-3169085035”

- NHTSA Complaint on June 26, 2017 for 2012 Equinox-“WE BUY THIS CAR FROM CHEVROLET COMPANY ON NOVEMBER 14,2011.

SINCE THAT TIME THE CAR WAS NOT IN OFTEN USE. UP TO ONE YEAR IT IS WAS IN THE STORAGE

WHEN WE BEGAN TO USE IT REGULAR WE NOTE THAT THE ENGINE HAS SOME FACTORY DEFECT, THE ENGINE OIL IS OFTEN DID NON RECEIVE TO EVEN 5000 MILES, AT THE 2500 MILES ESTIMETELY, WE WERE FORCE TO ALWAYS CHANGE OIL, THE OIL COLOR OF THE ENGINE WAS ALWAYS VERY BLACK AS DIRTY, WE ALWAYS WERE WONDERING, WHY THE COLOR OF THE ENGINE OIL IS TURNS VERY BLACK, LIKE WE DID NOT CHANGED IT FOR LONG TIME.”

- NHTSA Complaint on May 31, 2017 for 2012 Chevrolet Equinox-“BOUGHT USED AND THEN STARTED NOTICING OIL DISAPPEARING. TOOK TO DEALER, OIL CONSUMPTION TEST DONE, DEALER SAYS NORMAL USE. NO HELP FROM THE DEALER AT ALL. CONSUMPTION GOT WORSE, WENT FROM 2 QUARTS TO 4 QUARTS BETWEEN OIL CHANGES. IN THE MEANTIME HAD TO REPLACE CATALYTIC CONVERTER AND A CRACKED EXHAUST MANIFOLD AND NOW HAVE A CHECK ENGINE LIGHT INDICATING O2 SENSOR PROBLEM, GAS MILEAGE DROPPING TOO. AFTER RESEARCHING, THESE PROBLEMS SEEM TO BE CAUSED BY THE OIL USE ISSUE. ENGINE PROBABLY NEEDS NEW RINGS AND PISTONS (\$2500 AT THE DEALER) BUT OTHER INTERNAL DAMAGE MAY BE PRESENT SO COST MAY BE EVEN MORE. I FOUND ON THE INTERNET THAT GM HAD EXTENDED WARRANTY FOR THIS ISSUE BUT ONLY UP TO 7 YRS OR 120K MILES. SO, I AM OUT OF LUCK AND DEALER DID NOT MENTION THIS AS THIS STARTED WHILE STILL UNDER 120K MILES. CONSULTED A HONEST MECHANIC FRIEND AND HE SAYS IT WOULD BE CHEAPER TO REPLACE THE ENGINE. HE QUOTED \$1800 FOR ENGINE AND LABOR, TURN KEY JOB, WITH A ONE YEAR WARRANTY ON EVERYTHING. I TRUST HIM. ONLY CHOICE IS TO REPLACE ENGINE OR GET RID OF THE CAR.”
- NHTSA Complaint on May, 26 2017 for 2012 Chevrolet Equinox-“THIS VEHICLE HAS KNOWN OIL CONSUMPTION ISSUES. IN

APRIL 2016 THE VEHICLE WAS LURCHING AND SHAKING. DURING SERVICE OF THE VEHICLE THEY STATED THE OIL WAS LOW, WHICH HAS BEEN AN ONGOING ISSUE. WE WERE ADVISED TO BRING IT BACK IN AUGUST FOR AN OIL CONSUMPTION TEST. WE TOOK IT IN FOR THE OIL CONSUMPTION TEST. NOW IN MAY 2017 WE ARE EXPERIENCING THE SAME ISSUES. INTERESTINGLY ENOUGH THE DEALERSHIP NOW HAS NO RECORD OF THE OIL ISSUES, INCLUDING THE OIL CONSUMPTION TEST. THE DEALERSHIP RUMMAGED THROUGH THE GLOVE COMPARTMENT AND STATED THE VEHICLE WAS ONLY GETTING OIL CHANGES EVERY 6000. IN FACT, NOT ALL OF THE OIL CHANGE RECEIPTS GO IN THE GLOVE COMPARTMENT. WE BELIEVE GM IS ATTEMPTING TO HIDE THE ISSUE. ULTIMATELY THE VEHICLE WILL LURCH AND CAUSE PERSONAL INJURY OR PROPERTY DAMAGE.”

- NHTSA Complaint on May 5, 2017 for 2012 Chevrolet Equinox: ”THE CONTACT OWNS A 2012 CHEVROLET EQUINOX. WHILE DRIVING 55 MPH, THE VEHICLE RATTLED AND MADE A HOST OF NOISES, WHICH INDICATED THAT THERE WAS NO OIL IN THE VEHICLE. THE CONTACT STATED THAT TWO QUARTS OF OIL WERE PLACED IN THE VEHICLE, BUT IT PREMATURELY DISSIPATED BEFORE THE INTENDED MILEAGE MARK. THE CONTACT STATED THAT OIL WAS ADDED TO THE VEHICLE THREE TIMES IN A SHORT PERIOD OF TIME. THE VEHICLE WAS TAKEN TO THE DEALER WHERE IT WAS DIAGNOSED THAT THERE WAS AN OIL CONSUMPTION FAILURE. THE VEHICLE WAS NOT REPAIRED, BUT THE CONTACT MADE AN APPOINTMENT WITH THE DEALER. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 91,000.”
- NHTSA Complaint: [2012 Chevy Equinox]-“ON APRIL, 13 2017, MY WIFE WAS EXITING THE HIGHWAY ON THE WAY HOME FROM WORK. THE VEHICLE IMMEDIATELY SLOWED AND SHUT DOWN NEARLY CAUSING HER TO BE RUN OVER BY A SEMI-TRACTOR BEHIND HER. BECAUSE THE CAR COULD NOT BE RE-STARTED, I HAD IT TOWED TO MY USUAL MECHANIC. HIS DIAGNOSIS SHOWED IT HAD A TIMING CHAIN FAILURE WHICH TORE UP THE UPPER END OF THE MOTOR. IN HIS EXPERIENCE SUCH DAMAGE WAS THE RESULT OF OIL ISSUES. THIS CAME AS A GREAT SHOCK TO

MEASURE I REGULARLY CHANGE THE OIL EVERY 3000 MILES. I WENT HOME THAT NIGHT AND BEGAN TO RESEARCH THIS PROBLEM AND HAVE FOUND THAT THIS IS NOT A RARE OCCURRENCE WITH THIS MOTOR. I WOULD HAVE TO ADD FROM 1-3 QUARTS OF OIL BETWEEN CHANGES BUT BECAUSE THERE WERE NO BULLETINS OR RECALLS I WAS TOLD I WOULD JUST HAVE TO DEAL WITH IT. SO I GUESS I NEED TO KNOW HOW MANY OF THESE VEHICLES HAVE TO DIE IN TRAFFIC OR PEOPLE HAVE TO DIE OR BE INJURED BEFORE SOMEONE TAKES NOTICE. I WILL HAVE TO REPLACE MY MOTOR (OVER \$5000) AND GM KNOWS THESE PROBLEMS EXIST. IT WAS JUST A MATTER OF TIME. AND TO ADD INSULT TO INJURY, GM EXPECTS ME TO HAVE THE VEHICLE TOWED TO THEIR FACILITY AT MY EXPENSE SO THEY CAN CONFIRM THE DIAGNOSIS. IF THE DIAGNOSIS IS CONFIRMED, THEN I'LL HAVE TO TOW IT BACK TO MY GUY SO HE CAN FIX IT. ANOTHER \$200 BUCKS. ONCE AGAIN, DOESN'T ANYONE MONITOR THE INTERNET ABOUT THIS STUFF? PEOPLE GET SO FRUSTRATED WHEN DEALING WITH LARGE CORPORATIONS, THEY HAVE NO CHOICE BUT TO SHARE THEIR STORIES WITH INDEPENDENT SOURCES. AND GM SURELY WON'T INCUR ADDITIONAL EXPENSES WITHOUT GOVERNMENT SCRUTINY. WE'VE LEARNED THAT THE HARD WAY. I JUST WANT THEM TO DO THE RIGHT THING. ADMIT IT WAS A PROBLEM-PLAGUED MOTOR AND FIX IT. THANK YOU FOR YOUR TIME."

- NHTSA Complaint on April 13, 2017 for a 2012 Chevrolet Equinox- "GOES THROUGH 4 QUARTS OF OIL BETWEEN OIL CHAGES WHICH ARE DONE EVERY 3 THOUSAND MILES. OIL LIGHT DOES NOT COME ON WHEN YOU ARE 3 QUARTS LOW."
- NHTSA Complaint on October 8, 2016 for a 2012 Chevrolet Equinox- "TL\* THE CONTACT OWNS A 2012 CHEVROLET EQUINOX. THE CONTACT STATED THAT THE CHECK OIL ENGINE WARNING INDICATOR ILLUMINATED. THE CONTACTED ASSUMED THAT THE OIL NEEDED TO BE CHANGED. THE VEHICLE WAS TAKEN TO THE DEALER WHERE IT WAS DIAGNOSED AS EXCESSIVE OIL CONSUMPTION. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE ISSUE. THE FAILURE MILEAGE WAS 94,000."

- NHTSA Complaint on March 2, 2017 for a 2012 Chevrolet Equinox:  
“CHECK ENGINE LIGHT CAME ON. CAR HAD BEEN IDLING ROUGH AND WOULD ALMOST STALL OUT AT RED LIGHTS. ALSO MADE A TICKING NOISE WHEN PRESSING ON THE ACCELERATOR AT ABOUT 20-25 MPH. I TOOK IT TO THE MECHANIC AND HE FOUND THE OIL LEVEL LOW. PERFORMED AN OIL CHANGE AND CLEARED THE DIAGNOSTIC CODE. HE ALSO GAVE ME INFORMATION PERTAINING TO THIS EXCESSIVE OIL CONSUMPTION BULLETIN. NOW I WILL HAVE TO CHECK MY OIL LEVEL AND MAKE SURE TO GET AN OIL CHANGE EVERY 3000 MILES.”
- NHTSA Complaint on April 03, 2017 for a 2013 Chevrolet Equinox-  
“USING WAY TO MUCH OIL. VERY DISAPPOINTED. I BUY A CAR TO KEEP LONG TERM. PRETTY OBVIOUS THIS PROBLEM WAS WELL KNOWN BY AUTOMAKER. I WAS NEVER NOTIFIED. WILL NEVER BUY A GM AGAIN!!!!”
- NHTSA Complaint on March 16, 2017 a 2013 Chevrolet Equinox: ”I HAD 100,000 MILES ON MY CHEVY EQUINOX AND IN DECEMBER WITH OUT WARNING THE ENGINE BLEW UP. I HAD RECENTLY HAD A OIL CHANGE BUT WAS TOLD THE ENGINE BARELY HAD ANY OIL. I HAD ARRIVED AT A DOCTORS OFFICE WAS THERE FOR A HOUR AND WHEN I WENT TO START MY CAR IT WAS COMPLETELY DEAD. I HAD TO REPLACE THE ENGINE.”
- NHTSA Complaint on March 20, 2015 for a 2013 Chevrolet Equinox:  
“TL\* THE CONTACT OWNS A 2013 CHEVROLET EQUINOX. WHILE DRIVING AT AN UNKNOWN SPEED, A LOUD ABNORMAL TICKING SOUND EMITTED FROM THE VEHICLE WITHOUT WARNING. THE VEHICLE WAS TAKEN TO A DEALER WHERE IT WAS DIAGNOSED THAT THERE WAS NO OIL IN THE VEHICLE. THE TECHNICIAN PERFORMED AN OIL CHANGE AND COMPRESSION TEST EVERY 1,000 MILES. THE CONTACT WAS INFORMED THAT THE PISTON IN THE ENGINE FAILED AND NEEDED TO BE REPLACED. THE VEHICLE WAS REPAIRED, BUT THE FAILURE RECURRED. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC WHERE THE TECHNICIAN STATED THAT THE VEHICLE WAS BURNING OIL RAPIDLY. THE VEHICLE WAS NOT REPAIRED. ON ANOTHER OCCASION, THE VEHICLE FAILED TO SHIFT GEARS PROPERLY. THE VEHICLE WAS TAKEN TO THE DEALER

WHERE IT WAS DIAGNOSED THAT THE TRANSMISSION NEEDED TO BE REPLACED. THE TRANSMISSION WAS REPAIRED WITH UNKNOWN PARTS. THE CONTACT ALSO STATED THAT THE WINDSHIELD WIPERS FAILED TO OPERATE INTERMITTENTLY. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 33,000.”

- [www.carcomplaints.com](http://www.carcomplaints.com) on July 10, 2015 for a 2012 Chevrolet Equinox: I had the exact same issues as everyone else. The 2012 Equinox started to sound like an old Model T and would die at red lights. I took to our mechanic and he said there was no oil in the car! He called the Chevy rep for us which came to look and told him we needed a new engine because we let it run with no oil. Our mechanic said well I change their oil every 5,000 miles so I know that's not true. The rep said they need to be changing every 1,000 miles! We could not believe it so I called Detroit. GM said this was normal and my husband should be putting oil in it all the time. We went with a brand new engine because were told if we put an old one in the same thing would happen again. Once its paid off it will be gone! We will never buy another Chevrolet again! Now my daughter drives it, we taught her how to check the oil and add if needed! OMG REALLY????
- [www.carcomplaints.com](http://www.carcomplaints.com) on May 27, 2015 for a 2012 Chevrolet Equinox: “I had 2 oil consumption tests done in 2015 before 100,000 miles and was told both times that my car "met the specs". I have to travel around with quarts of oil in my car because I constantly have to check the oil and fill it up.

I recently received a letter from Chevrolet stating that they now acknowledge an oil consumption problem with this model year Equinox. My problem is I now have 138,000 miles and the fix is for vehicles with less than 120,000 miles. Neither my car dealership (Anoka MN) or Chevrolet are willing to fix the problem because I now have over 120,000 miles, even though I was having the problem below 100,000 miles.

I am definitely angry about this and am going to go to the top to address this issue. I'd like to know why 120,000 miles is the "magical number" for mileage. I am looking for a new vehicle and will not buy an Equinox and will not buy a Chevrolet. I feel I have not been dealt with fairly.”

- [www.carcomplaints.com](http://www.carcomplaints.com) on June 6, 2017 for a 2012 Equinox—"I BOUGHT A 2012 CHEVROLET EQUINOX WITH APPROX 2000 MILES AT TIME OF PURCHASE. AROUND 20,000 MILES I NOTICED IT USING OIL BETWEEN OIL CHANGES. TOOK IT TO CHEVROLET IN 2015, TOLD THEM THE PROBLEM. THEY REPLACED THE SEAL WITH OIL FILTER. THE LAST YEAR IT HAS STALLED, ENGINE KNOCK AND STILL USING MORE OIL. I GOT A LETTER MAY 2017 SAYING I NEED TO TAKE THE EQUINOX TO CHEVROLET DEALER IF I HAVE ANY PROBLEMS STATED IN THE LETTER, WHICH I HAVE AND STILL DO. THEY TOLD ME I HAD TO DRIVE IT 500 MILES, BRING IT BACK TO DO A ENGINE OIL PRESSURE TEST. AM STILL DRIVING IT. AFRAID TO BUT VERY WORRIED AND CONCERNED ABOUT THIS PROBLEM."
- [www.carcomplaints.com](http://www.carcomplaints.com) on December 2, 2015 for a 2012 Chevrolet Equinox: "The problem started around late 2015 had almost 100,000 miles on the car started using more oil than usual. Didn't think there was a problem but it got worse as time went on started adding two quarts of oil between oil changes. Now I'm up to 3 quarts of oil between oil changes I didn't realize there was a problem until I got a letter from GM saying that they would repair the problem. But now I have a 148000 on the car and it's out of warranty, so now what do I do."
- [www.carcomplaints.com](http://www.carcomplaints.com) on October 1, 2016 for a 2012 Equinox—"I own a 2012 Equinox LS. I bought the vehicle used with only \$25,000 miles. At around \$35,000 miles the timing chain had to be replaced. Shortly after I had to start an oil consumption test, the vehicle was not running well and the engine was ticking. No oil on the dipstick and vehicle was not even close to the next oil change due. I'm now at \$44,000 miles and still doing the oil consumption test.

This time the Engine is knocking very loudly, no oil on dipstick again, yellow bubbly fluid and the smell of gas. Dealer tops it off - down 3 quarts this time. Come back again between \$1,500 and \$2,000 miles.

I was told by the dealership that GM has a special warranty for the engine in the 2012 Equinox because they are aware of the problem. I was told the pistons are probably bad - and this was said to me when we first started the oil consumption test, but I need to do this test in order to prove to GM there is a problem. Hoping this is true.

At this point I'm very aggravated and worried the engine will go one day while I'm driving."

- [www.carcomplaints.com](http://www.carcomplaints.com) on February 28, 2017 for a 2012 Equinox-“I purchased my 2012 Equinox new, late in 2011. It now has just over 80,000 miles. I have done all routine maintenance on the vehicle but a couple days ago the check engine light came on... so I brought it in for service at my dealer. I was told that my vehicle had NO oil... nothing was registering on the dip stick at all! I was told that this is a prevalent problem with this make and model... that I needed to check my oil every 1000 miles now and that I may need to get my pistons etc.. replaced. Estimate...\$2500.00 ! That was yesterday... and today the same check engine light is on. OnStar diagnosis today... same problem. In reading the same problem over and over again on this site, something needs to be done and there needs to be a recall!”
- [www.carcomplaints.com](http://www.carcomplaints.com) on August 20, 2016 for a 2012 Chevrolet Equinox -“I bought this car about 2 years ago and for some reason every time I check the oil, the oil is low, even after an oil change. This is ridiculous. I just don't understand how a car consumes oil. I took it to the dealership and they don't understand why it does that. I took to the mechanic to check for leaks, nothing. So where the hell is the oil going if its not leaking? I wish I knew this before I bought this car because I see big problems with this in the future because my wife drives this car and she doesn't know anything about cars. She takes my kids to daycare every morning. I keep up with all maintenance that needs to be done, but I have a feeling my heads are going blow or something bad is going to happen if this problem is not resolved.”
- [www.carcomplaints.com](http://www.carcomplaints.com) on June 1, 2015 for a 2012 Equinox-“We purchased a used 2012 Chevrolet Equinox used in early 2015 with a little over 27,000 miles showing on the odometer and were well pleased with vehicle at the time. About a thousand miles later, I was checking the oil and noticed it was low...had to add about 1/2 quart or so to top it off. I thought this was unusual since it just had a fresh change when we bought it. When I changed the oil about three thousand miles later, it was almost a quart low then. The engine now has a little over 45,000 miles on it and I'm having to add about 1-2 quarts in between oil changes, which is ridiculous for a modern engine. Searching through the internet tonight, I'm seeing this is a common issue for these engines that is being blamed on a faulty engineering piston / ring / timing chain design. Has anyone else had any luck getting GM to stand behind their product and correct the problem or am I just stuck with keeping a case of oil around all the time? I'm going to make it my life's calling to tell everyone about this and warn them off this vehicle. We've always bought Ford products in the past and I was hesitant about buying a Government Motors

product, wished now that had trusted my gut on this purchase.”

- [www.carcomplaints.com](http://www.carcomplaints.com) on July 1, 2016 for a 2012 Chevrolet Equinox Do not buy this vehicle. First day I bought it we had to get the timing chain replaced. The check engine light stays on. A part that had to do with the gas had to be replaced. Now I am dealing with the engine oil consumption issue. BTW the warranty is up at 100,000 mine is at 128,000. I'm burning a quart a week.
- [www.carcomplaints.com](http://www.carcomplaints.com) on June 1, 2014 for a 2012 Chevrolet Equinox This car uses excessive oil. I drive several miles a day. I have mentioned this to the local dealer and they gave me a list of items to "fix" which cost several thousand dollars. I have to monitor my own oil because the oil light does not come on when it is real low. It does come on when it is time for the oil to be changed. I have owned several Chevrolet vehicles but this one has caused me the most problems. I have called and there does not appear to be a recall or legitimate explanation as to why the car uses so much oil. I do not have a leak on the ground.
- [www.carcomplaints.com](http://www.carcomplaints.com) on July 17, 2015 for a 2012 Chevrolet Equinox Since the day I bought this vehicle, it has eaten oil. I drive the car about 100 miles a day and have to add at least 2 quarts a week. I have spoken to other Equinox owners and they all seem to have the same issue. Around a quart for every 1000 miles.
- [www.carcomplaints.com](http://www.carcomplaints.com) on December 15, 2017 for a 2012 Chevrolet Equinox This car has used a quart of oil every 1000 miles from day one....mentioned to my mechanic at regular scheduled oil changes and was always told it was normal. Upon looking into my constant complaint my mechanic recommended to file a complaint as this oil consumption seems to be a big problem. This should be recalled if Chevy was reputable. This is the second Chevy and probably the last I will purchase, as much as it cost to purchase a nice vehicle you should not have to deal with these big issues from day one. Engine should be recalled and replaced , not at the owners expense.
- [www.carcomplaints.com](http://www.carcomplaints.com) on June 16, 2016 for a 2012 Chevrolet Equinox-“Wife was driving to work and car stopped on highway wouldn't start. She called me crying because she loves that car. Got it to the local dealership and said it had no oil. Told them there is no way that I just checked it a few days ago and topped it off. They tell me those engines are bad for going through oil and that the warranty won't fix the problem because all my paper work got thrown away. If GM

knows about the oil problem in these wouldn't you think they would make it right? GM is garbage vehicles, don't buy anything GM.”

- www.carcomplaints.com on June 20, 2016 for a 2012 Chevrolet Equinox: “We just found out that the Equinox is known for burning excess oil. We never expected to have to check the oil frequently on a new vehicle. The engine light came on so my husband checked the oil, as it was due for an oil change, and there was no oil on the dipstick! He immediately took it the next morning to the dealership in Washington, IL. They told him that GM is aware of the problem and will replace the engine. How long have we been driving it with no oil in it? It doesn't say that the oil level is low. The engine has to be ruined! We won't be buying another Chevy.. We have to check the oil every 1,000 miles until the next oil change. If it qualifies as a problem we will get a new engine. On a fairly new car...Really??”
- www.carcomplaints.com on November 11, 2015 for a 2012 Chevrolet Equinox: “Suddenly I noticed a rattling sound that got worse over time. I was leaving work when a co-worker heard the noise, came over and popped the hood to check the oil level. The stick was dry! He asked me to go into the shop (I work at a dealership Not Chevrolet) so he could put some oil in for me. He put in two quarts and said come in tomorrow for a more thorough check. Engine was down three quarts. Gave me a complete oil change and sent me on my way.

Here it is Feb and the same thing happened. Down four quarts of oil! Taking it to Chevy for the inevitable run around. I've dealt with them before for other issues. Never a solution. The service writers always give me the feeling that I am someone to avoid like the plague and I get never a solution . It's all in my head. Never again will I buy a Chevrolet. #mycheysucks”

- www.carcomplaints.com on April 15, 2015 for a 2012 Chevrolet Equinox—“I purchased this 2012 Chevy with intentions of it being my last car. I normally purchase foreign cars because I strongly believe in the engines. This car burns all of the oil after an oil change in less than 30 days. I have my car serviced on 4/17/2015 and after checking oil before a road trip on 5/11/2015 it was barely on dipstick. After driving to Atlanta less than 300 miles I had to add more oil. Using synthetic blend gets expensive. I would never recommend this car to anyone. The dealer is not at fault but Chevy is because they have received numerous complaints. They claim bad oil rings and can be repaired for approx. \$2500”

- [www.carcomplaints.com](http://www.carcomplaints.com) on June 26, 2015 for a 2012 Chevrolet Equinox: "We noticed our engine was rattling and decided we should check the oil. It was down 2 quarts so we added oil and since it was about time for an oil change, we had it changed. We are now 3,000 mile into this oil change and have already added oil. We will be contacting the dealership to see if there is a fix for this that isn't going to cost us an arm and a leg. There is now 72,332 miles on this engine and we use Royal Purple Performance synthetic oil."
- [www.carcomplaints.com](http://www.carcomplaints.com) on June 25, 2015 for a 2012 Chevrolet Equinox-"I was a victim of the excessive oil consumption problems that, I now understand are common with the Chevy Equinox. I did not know that the oil was low, which I had the road and called AAA. changed approx 4000 miles before. I first became aware of the problem when my engine would stop each time I stopped at an intersection. I was on the way to my repair garage when I heard a rather loud noise coming from the engine compartment. Pull over to the side of  
Car was towed to my normal service garage. My mechanic could not help so I had the car towed to Lawrence Chevrolet in Mechanicsburg, Pa. A diagnostic check was made and the dealership said that I needed a new engine and that my warranty would not cover the cost of the repairs. Estimated costs to me would be about \$6000. I did not authorize the dealership to fix the vehicle due to the cost. Now looking for another way to get the problem fixed."
- [www.carcomplaints.com](http://www.carcomplaints.com) on December 1, 2014 for a 2012 Chevrolet Equinox-"I will never buy another Chevy in this lifetime. I will also let everyone I come in contact with know about this issue. My 2012 Chevy Equinox (JUNK) has about 1,500 miles on the new Dexos (Recommended Oil) It sounds like a diesel, dies at red lights, and if I check the oil level there isn't one! Problem here? Absolutely! Will Chevy cover this under their "100,000 mile powertrain warranty? NO! Is this false advertisement on their part? YES! My advice to everyone out there. DO NOT BUY A CHEVY OR ANY OTHER VEHICLE THEY ARE AFFILIATED WITH! CHEVROLET IS JUNK!!!! Thank you for reading! Rant over because it is a waste of my breath to talk any more about this auto maker!!!!"
- [www.carcomplaints.com](http://www.carcomplaints.com) on November 1, 2012 for a 2012 Chevrolet Equinox "The car uses about 1-2 quarts between oil changes, which Chevy recommends at 7,500 miles (using synthetic oil). Every oil change they need to put in 1-2 quarts. Chevy states it is "normal" for their cars to use oil, as much as 1 quart every 2,000 miles (and that's a

quote from a Chevy service representative). I have been driving for over 40 years and have never had a car use that much oil.”

- [www.carcomplaints.com](http://www.carcomplaints.com) on February 6, 2013 for a 2012 Chevrolet Equinox -“Purchased this vehicle and assured by the dealer that I was getting a great deal. I travel ALOT and use my personal vehicle for it. I was in the habit of checking my oil dipstick level every few fill ups. I took it in to the dealer to have it looked at when I noticed that the oil consumption was about a quart every 1000 miles. I was told then that "Yea, you have to keep an eye on your oil level and check it frequently.

My complaint is that if it is known that the engine consumes a quart of oil every 1000 miles, why is it NOT in the manual? Why did the dealer NOT tell me that this is a known problem when I bought it? Why does the manual tell you to change the oil every 4 - 5 k miles? By the time you go to change the oil you have been out of oil and have damaged the engine. I am a mechanical tech and you can not possibly tell me that this is an expected issue for an engine. Why hasn't Chevy installed an oil level sensor to tell the owner that the oil level is low?

I cant wait to get out of this vehicle and will not buy another Chevy due to the way I have been treated as to this. I have been treated as if it is MY fault. I have 95,000 miles on it. That would be about 70 quarts of oil added to it. It is not the cost as much as it is what damage has been done to this engine from this. The car is in the shop right now for stalling. My regular mechanic says it is the cam position sensor that usually does this when the oil gets sludgy due to being low occasionally.”

- [www.carcomplaints.com](http://www.carcomplaints.com) on April 2, 2010 for a 2010 Chevrolet Equinox: “As a consumer that works extremely hard for her \$\$\$ I'd like to for warn you about what your future could hold if you purchase a brand new vehicle with GM Canada. I bought the 2010 Chevy Equinox – base model, no extras, brand new. I really love(d) this car, I was beyond happy with the look, the drive, everything ... that is until 20,000km hit when my car began to sound like it had a diesel engine. When I returned 2 days later for an oil change – I was told the car had a major oil leak. I live in a new home, new driveway – and there was no oil on the ground. Where is all this oil going? So I went on an oil consumption report to help GM understand the issue. For 10,000km I had to visit the dealership every 1000km so that they could monitor the issue. This is my oil history: I worked very closely with my dealership for the next several months to try and determine the cause. They changed belts and did other small

repairs, however the engine continued to always go back to this noise? One day I was driving the vehicle and it began to shake vigorously at a stoplight, so I went straight to the dealership and they told me my car had no oil in it?! Weird, the oil light never came on! Nor did the engine light, yet the car was on the verge of the engine seizing – scary! So those sensors, don't depend on them! I'm glad I was city driving, and not on the highway that day. June 30th – 2 ½ liters added July 2nd – Engine required shampooing due to excessive oil leak, dye ball placed in oil tank to determine where the oil came from. July 12th – Drop off car for overnight service to determine where the oil was leaking from July 13th – Told a part has been ordered, gasket cover broke and needed to be replaced, once done I'll go back on the oil consumption report. Still very concerned that I'm being told I had a massive leak yet no trace of oil on my driveway? July 26th – add 500ml of oil Aug – 1.5 liters added, GM recommends decarbonizing before taking engine apart Aug 22nd – drop off car for the decarbonizing, pick up then come back in 1000km Sept 8th – 350ml added, told I may need to have the engine pulled apart Sept 20th – Was told the car was fine, no oil burned Oct 7th – 1.5L added, told to call my service adviser on Monday to schedule the drop off and get me in a rental so they can take a part the engine. I truly believe that because this issue clearly began back at 20,000km I voiced that I did not want them to rebuild, instead I wanted them to replace the engine. I've put so much money into maintaining the car that I felt it was only fair, but GM said their policy is to take apart the engine to find the problem. I once again voiced my concern that the oil & engine light did not come on, they said they'll look into it. I also would like them to tell me if the line my vehicle came off of, has anyone else experienced this issue? Because I've read other people's blog's saying they had the same problem I'm having so I'm wondering, did their car come from the same line as mine? I told them the reason I wanted (and felt I deserved) a new engine was because of the maintenance I've put into trying to prolong the life of the car by doing all recommended service. If you take the fact that the issue began at 20,000km and I'm now at 65,000km and it's still occurring, plus the fact that they have no idea why it's burning oil, how can they be sure it hasn't caused any other damage to my engine? I'm not a service technician so how do I know that this oil issue isn't contributing or causing other strains that may not be visible now however could develop down the line from this unknown reoccurring problem? If I didn't do all the recommended service I'd be ok ... well not ok, but I'd understand the rebuild. But why did I pay for all that extra service? To me this appears to be a manufacturer's defect (unknown burning oil/sensors don't respond) and not regular wear and tear. I mean, hey, if the oil in your vehicle wasn't an important factor, why do we all do oil changes? Aren't we

all told that by not doing oil changes along with other maintenance were decreasing the life of a vehicle? Yet I was told by GM Customer Care – “Ma’am, the issue will be noted on file for future reference” – that’s reassuring, right? So, now, after I’ve been able to share my story I hope this helps you in your decision in purchasing a new GM, or any new car for that matter. I always tell myself to learn from my misfortunes and today I’ve learned that when I’m thinking about buying another vehicle I will buy used, for sure. If I knew that buying new would provide me with this kind of service and reliability I would have definitely explored more options. I made the mistake of thinking that by buying a new vehicle I would have assurance that I would have a reliable vehicle, and that with maintenance I could hopefully get a good life out of the car, for my family. I was mistaken. ☹️P.S. If I’m wrong PLEASE educate me cause I have no idea how cars work, I’m basing my feeling purely on business, product and ethics, so I’d love some feedback – bad or good please.

- [www.carcomplaints.com](http://www.carcomplaints.com) on September 1, 2010 for a 2010 Chevrolet Equinox: “What kind of engine burns a litre (quart) every 1000km (620miles)? A 2.4L 4cyl piece of garbage from GM, that's what kind! Maybe the engine just needs to be broken in. Nope, that's not it. Maybe it needs synthetic. Nope, not that either. The geniuses at my dealership were pretty stumped when I approached them back in 2010 with this problem. They told me I had to do something called an "oil report" to confirm that it was burning oil. Cause that's something that people lie about? Regardless, This process involves me driving out of my way to the dealership everytime I get low on oil - which is about every 2nd tank of gas. What if I'm out of town? "Well...try to get topped up before you go". Right, because I have time for that. Huge inconvenience? Absolutely. Apparently this oil report was a huge inconvenience for them as well. Every time I showed up at the dealership to get oil added, they treated me like a second class citizen. So I gave up on the oil report and resigned myself to adding a litre at every 2nd fill up. Now, 4 years later I read online that some people are getting their engines replaced as a result of excessive oil consumption! Thanks CARCOMPLAINTS.COM! I'll be working on my dealership to replace my engine. Then I will be trading in my Equinox for an import.”
- [www.carcomplaints.com](http://www.carcomplaints.com) on June 1, 2010 for a 2010 Chevrolet Equinox: “Bought my 2010 Equinox new. Really like the car, except for the oil consumption problem. Engine used a quart of oil each 1,000 miles. I put up with it for several years. Then, at 50,000 miles, I took it to Bridgewater Chevrolet. Oil consumption test showed excessive oil consumption. Dealer replaced the pistons and rings under

warranty. That was 1,000 miles ago. Engine shows no sign of excessive oil consumption now. Should have done this 5 years ago, but I had heard that GM was resistant to making needed repairs when the problem was first being discovered. Now, I assume, with a mountain of evidence and complaints, GM is doing the right thing and repairing engines under warranty. If you own this car and have an oil problem, don't wait. Take it to the dealer for test and repair. The dealers have a bulletin from GM about the issue, so they are expecting to hear from you.”

- www.carcomplaints.com on September 15, 2009 for a 2010 Chevrolet Equinox: “Amazingly, after several trips to Len Stoler for an oil consumption test. they said that it never used more then a quart of oil per thousand. I decided to check their honesty. I drained and oil and made sure it was 1.5 quarts low. Amazingly according to Len Stoler, it didn't use more then a quart. That's when I stopped taking it for the oil consumption test.”

183. GM failed to conduct sufficient testing during the design phase of the 2.4L engine. As a result, GM has caused Plaintiffs and Class Members to spend money at its dealerships or other third-party repair facilities and/or to take other remedial measures related to the Oil Consumption Defect in the Class Vehicles, such as having additional oil containers in the Class Vehicles at all times.

184. Despite its knowledge of the Oil Consumption Defect, GM's policy when owners or lessees of Class Vehicles complain to GM specifically about that defect, is only to tell the customer to bring the vehicle in every 500 miles for an oil check, although GM has and had knowledge that there was excessive oil consumption as a result of utilizing faulty piston rings and related defects.

185. GM has never fully disclosed the Oil Consumption Defect to consumers. Instead GM attempted to squelch public recognition of the Oil Consumption Defect by propagating the falsehood that the excessive oil consumption that drivers of the class vehicles have experienced is “not excessive” or is “normal.”

186. GM has allowed drivers of the Class vehicles to continue driving those vehicles, despite knowing that they are consuming oil at an abnormally high rate, and has continued allowing drivers of the Class Vehicles to rely on the Oil Life Monitoring System, despite knowledge that system give the driver a false sense of security, and despite knowing that the OPW system does not give notice that the vehicle has less than the amount of oil necessary for proper engine lubrication and proper, safe operation. As a result, Class Vehicles suffer engine failure and engine damage, including spark plug fouling, ring wear, lifter collapse, bent pushrods, camshaft wear, valve wear, rod bearing wear, rod breakage, wristpin wear, wristpin breakage, crankshaft wear and main bearing or destruction and other forms of internal component wear/breakage due to unacceptable heat and friction levels and oil breakdown.

187. GM has not recalled the Class Vehicles to repair the Oil Consumption Defect, and has not offered to reimburse Class Vehicle owners and lessees who incurred costs relating to excessive oil consumption and related problems.

188. Plaintiffs and Class Members are reasonable consumers who do not reasonably expect their Class Vehicles to require the addition of oil between regularly scheduled oil changes in normal service, or for their engines to consumer more than one quart of oil between regularly schedule oil changes.

189. Plaintiffs and Class Members reasonably expected that GM would not sell or lease Class Vehicles with known defects, such as the Oil Consumption Defect, and that it would disclose any such defects to its consumers before they purchased or leased the Class Vehicles. Plaintiffs and Class Members did not expect GM to conceal the Oil Consumption Defect, or to continually deny its existence.

190. Consequently, Plaintiffs and Class Members have not received the benefit for which they bargained when they purchased or leased the Class Vehicles.

191. As a result of the Oil Consumption Defect, the value of the Class Vehicles has diminished, including without limitation the resale value of the Class Vehicles.

## **TOLLING OF THE STATUTE OF LIMITATIONS**

### **A. Discovery Rule Tolling**

192. Plaintiffs could not have discovered through the exercise of reasonable diligence that their Class Vehicles were defective within the time period of any applicable statutes of limitation.

193. Among other things, neither Plaintiffs nor the other Class members knew or could have known that the Class Vehicles are equipped with 2.4L engines with the Oil Consumption Defect, which causes those engines to consume oil at an abnormally high rate and to sustain engine damage resulting therefrom.

194. Further, Plaintiffs had no knowledge of the defect and it occurred in a part of the engine that was not visible to consumers. GM attempted to squelch public recognition of the Oil Consumption Defect by propagating the falsehood that the excessive oil consumption that drivers of the class vehicles were experiencing was “normal.” Accordingly, any applicable statute of limitation is tolled.

### **B. Fraudulent Concealment Tolling**

195. Throughout the time period relevant to this action, GM actively concealed from and failed to disclose to Plaintiffs and the other Class members vital information about the Oil Consumption Defect described herein.

196. In the owner's letters sent by GM to its customers beginning in August 2014 associated with the MY 2010-2012 SCA's, GM instructed its customers:

[I]f this [excessive oil consumption] condition is present, the oil can light may illuminate on your instrument panel or you may have one of the following messages in the Driver Information Center: "Engine Oil Low - Add Oil" or "Oil Pressure Low - Stop Engine." . . . .

Do not take your vehicle to your GM dealer as a result of this letter unless you believe that your vehicle has the condition as described above.

(Emphasis added).

197. Because the OPW systems did not work reliably (or at all) on the Class Vehicles, and GM knew or was reckless in not knowing that this was the case, its instruction to customers to not take their vehicles to the dealer for inspection if the OLM warnings did not appear is tantamount to a deliberate concealment of the defect from Class Vehicle owners.

198. GM kept Plaintiffs and the other Class members ignorant of vital information essential to the pursuit of their claims. As a result, neither Plaintiffs nor the other Class members could have discovered the defect, even upon reasonable exercise of diligence.

199. Throughout the Class Period, GM has been aware that the 2.4L EcoTec engines it designed, manufactured, and installed in the Class Vehicles contained the Oil Consumption Defect, resulting in excessive oil loss and engine damage.

200. Despite its knowledge of the defect, GM failed to disclose and concealed, and continues to conceal, this critical information from Plaintiffs and the other Class members, even though, at any point in time, it could have done so through individual correspondence, media release, or by other means.

201. Plaintiffs and the other Class members justifiably relied on GM to disclose the Oil Consumption Defect in the Class Vehicles that they purchased or leased, because that defect was hidden and not discoverable through reasonable efforts by Plaintiffs and the other Class members.

202. Thus, the running of all applicable statutes of limitation have been suspended with respect to any claims that Plaintiffs and the other Class members have sustained as a result of the defect, by virtue of the fraudulent concealment doctrine.

### **C. Estoppel**

203. GM was under a continuous duty to disclose to Plaintiffs and the other Class members the true character, quality, and nature of the defective 2.4L EcoTec engines.

204. GM knowingly concealed the true nature, quality, and character of the defective 2.4L engines from consumers.

205. Based on the foregoing, GM is estopped from relying on any statutes of limitations in defense of this action.

### **CLASS ACTION ALLEGATIONS**

206. Plaintiffs bring this lawsuit individually and as a class action on behalf all others similarly situated pursuant to Federal Rules of Civil Procedure (“Rule”) 23(a), (b)(2), and/or (b)(3). This action satisfies the numerosity, commonality, typicality, adequacy, predominance, and superiority requirements of Rule 23.

207. The Class and Sub-Class are defined as:

Nationwide Class:

*All current and former owners or lessees of 2010 through 2017 model year Chevrolet Equinox equipped with a 2.4 liter engine (“the Nationwide Class”).*

Illinois Sub-Class:

*All Members of the Nationwide Class who reside in the state of Illinois and who purchased or leased their vehicles in the State of Illinois (“the Illinois Sub-Class”).*

208. Excluded from the Class and Sub-Classes are: (1) GM, any entity or division in which GM has a controlling interest, and its legal representatives, officers, directors, assigns, and successors; (2) the Judge to whom this case is assigned and the Judge’s staff; and (3) those persons who have suffered personal injuries as a result of the facts alleged herein. Plaintiffs reserve the right to amend the Class and Sub-Class definitions if discovery and further investigation reveal that the Class and Sub-Class should be expanded or otherwise modified.

209. Numerosity: Although the exact number of Class Members is uncertain and can only be ascertained through appropriate discovery, the number is great enough such that joinder is impracticable. The disposition of the claims of these Class Members in a single action will provide substantial benefits to all parties and to the Court. The Class Members are readily identifiable from information and records in GM’s possession, custody, or control, as well as from records kept by the Department of Motor Vehicles of various states.

210. Typicality: The claims of the representative Plaintiffs are typical in that Plaintiffs, like all Class Members, purchased and/or leased a Class Vehicle designed, manufactured, and distributed by GM with the Oil Consumption Defect. Plaintiff, like all Class Members, has been damaged by GM’s misconduct in that, *inter alia*, they have incurred or will continue to incur the cost of purchasing engine oil to replace the oil consumed by his defective engine. Furthermore, the factual bases of GM’s misconduct are common to all Class Members and represent a common thread of fraudulent, deliberate, and negligent misconduct resulting in injury to all Class Members.

211. Commonality: There are numerous questions of law and fact common to Plaintiffs and Class Members that predominate over any individual questions. These common legal and factual issues include the following:

- a) whether the Class Vehicles and their engines are defectively designed or manufactured such that they are not suitable for their intended use;
- b) whether the fact that the Class Vehicles suffer from the Oil Consumption Defect would be considered material to a reasonable consumer;
- c) whether, as a result of GM's concealment or failure to disclose material facts, Plaintiff and Class Members acted to their detriment by purchasing Class Vehicles manufactured by GM;
- d) whether GM was aware of the Oil Consumption Defect;
- e) whether the Oil Consumption Defect constitutes an unreasonable safety risk;
- f) whether GM breached express warranties with respect to the Class Vehicles;
- g) whether GM has a duty to disclose the defective nature of the Class Vehicles and the Oil Consumption Defect to Plaintiffs and Class Members;
- h) whether Plaintiffs and Class Members are entitled to equitable relief, including but not limited to a preliminary and/or permanent injunction; and
- i) Whether GM violated the consumer protection statutes of Illinois when it sold to consumer Class Vehicles that suffered from the Oil Consumption Defect.

212. Adequate Representation: Plaintiffs will fairly and adequately protect the interests of Class Members. Plaintiffs have retained attorneys experienced in the prosecution of class actions, including consumer and product defect class actions, and Plaintiffs intend to prosecute this action vigorously.

213. Predominance and Superiority: Plaintiffs and Class Members have all suffered and will continue to suffer harm and damages as a result of GM's unlawful and wrongful conduct. A class action is superior to other available methods for the fair and efficient adjudication of the controversy. Absent a class action, Class Members would likely find the cost of litigating their claims prohibitively high and would therefore have no effective remedy at law. Because of the relatively small size of Class Members' individual claims, it is likely that few Class Members could afford to seek legal redress for GM's misconduct. Absent a class action, Class Members will continue to incur damages, and GM's misconduct will continue without remedy. Class treatment of common questions of law and fact would also be a superior method to multiple individual actions or piecemeal litigation in that class treatment will conserve the resources of the courts and the litigants and will promote consistency and efficiency of adjudication.

#### **FIRST CAUSE OF ACTION**

##### **Breach of Written Warranties under the Magnuson-Moss Warranty Act 15 U.S.C. § 2301, *et seq.* (On behalf of the proposed Nationwide Class)**

214. Plaintiffs incorporate by reference the allegations contained in the preceding paragraphs of this Complaint.

215. Plaintiffs bring this cause of action individually and on behalf of the Nationwide Class against GM.

216. Plaintiffs and Class Members are "consumers" within the meaning of the Magnuson-Moss Warranty Act ("MMWA"), 15 U.S.C. § 2301(3).

217. GM is a "supplier" and "warrantor" within the meaning of 15 U.S.C. § 2301(4)-(5).

218. The Class Vehicles are "consumer products" within the meaning of 15 U.S.C. § 2301(1).

219. GM's express warranties are each a "written warranty" within the meaning of 15 U.S.C. § 2301(6).

220. GM extended a 3-year/36,000 mile New Vehicle Limited Warranty with the purchase or lease of the Class Vehicles, thereby warranting to repair or replace any part defective in material or workmanship at no cost to the owner or lessee. GM also extended a Powertrain Limited Warranty that covers the cost of all parts and labor necessary to repair powertrain components, including the engine, that are defective in workmanship and materials within five years or 100,000 miles, whichever occurs first, calculated from the start date of the Basic Limited Warranty with purchase of a Class Vehicle. The Limited Warranty Begins on the date in which the purchaser first put the vehicle into service. The Limited Warranty transfers automatically with the transfer of vehicle ownership during the warranty period. GM further extended a 7.5-year/120,000 mile Extended Warranty to Plaintiffs by letter.

221. GM breached these express warranties by:

- a) Selling and leasing Class Vehicles with engines that were defective in material and workmanship, requiring repair or replacement within the warranty period; and
- b) Refusing and/or failing to honor the express warranties by repairing or replacing, free of charge, any defective component parts.

222. GM's breach of express warranty has deprived Plaintiffs and Class members of the benefit of their bargain.

223. The amount in controversy of the Plaintiffs' individual claims meet or exceed the sum or value of \$50,000.00, and there are over 100 class members.

224. GM has been afforded a reasonable opportunity to cure its breach of written warranties, including, when Plaintiffs and Class Members brought their vehicles in for diagnosis and repair of their engines.

225. As a direct and proximate cause of GM's breach of written warranties, Plaintiffs and Class members did not receive the benefit of the bargain and suffered damages at the point of sale stemming from their overpayment for a Class Vehicle with a latent safety defect. GM's conduct damaged Plaintiffs and Class Members, who are entitled to recover actual damages, consequential damages, specific performance, diminution in value at the point of sale, costs, including statutory attorneys' fees and/or other relief as appropriate.

### **SECOND CAUSE OF ACTION**

#### **Violations of the Illinois Consumer Fraud and Deceptive Business Practices Act (On Behalf of the Proposed Nationwide Class and Illinois Subclass)**

226. Plaintiffs hereby incorporate by reference the allegations contained in the preceding paragraphs of this Complaint.

227. Plaintiffs bring this Count on behalf of the Nationwide Class and the Illinois Subclass.

228. Plaintiffs and the Nationwide Class and Illinois Subclass members are consumers under the Illinois Consumer Fraud Act and Defendant is a "person" within the meaning of 815 Ill. Comp. Stat. 510/1(5).

229. GM engaged, and continues to engage, in the wrongful conduct alleged herein in the course of trade and commerce, as defined in 815 ILCS 505/2 and 815 ILCS 510/2.

230. 815 ILCS 505/2 (Illinois Consumer Fraud Act) prohibits:

[u]nfair methods of competition and unfair or deceptive acts or practices, including but not limited to the use or employment of any deception, fraud, false pretense, false promise, misrepresentation or the concealment, suppression or omission of any material fact, with intent that others rely upon the concealment, suppression or omission of such material fact, or the use or employment of any practice described in Section 2 of the 'Uniform Deceptive Trade Practices Act,' approved August 5, 1965, in the conduct of any trade or commerce are hereby declared unlawful whether any person has in fact been misled, deceived or damaged thereby. In construing this section consideration shall be given to the interpretations of the Federal Trade Commission and the federal courts relating to Section 5(a) of the Federal Trade Commission Act.

231. 815 ILCS 510/2 provides that a:

person engages in a deceptive trade practice when, in the course of his or her business, vocation, or occupation," the person does any of the following: "(2) causes likelihood of confusion or of misunderstanding as to the source, sponsorship, approval, or certification of goods or services; ... (5) represents that goods or services have sponsorship, approval, characteristics, ingredients, uses, benefits, or quantities that they do not have...; (7) represents that goods or services are of a particular standard, quality, or grade... if they are not; ... [and] (12) engages in any other conduct which similarly creates a likelihood of confusion or misunderstanding.

232. The business practices of GM were unfair because GM knowingly sold Plaintiffs and the other Class members Class Vehicles with defective engines that are essentially unusable for the purposes for which they were sold. The injuries to Plaintiffs and the other Class members are substantial and greatly outweigh any alleged countervailing benefit to Plaintiffs and the other Class members or to competition under all of the circumstances. Moreover, in light of GM's exclusive knowledge of the Oil Consumption Defect, the injury is not one that Plaintiffs or the other Class members could have reasonably avoided.

233. GM provided, disseminated, marketed, and otherwise distributed uniform false and misleading advertisements, technical data and other information to consumers regarding the performance, reliability, quality and nature of the Class Vehicles such as that its Class Vehicles consumed a normal amount of oil per mile and had certain accurately calculated fuel economy numbers which is not the case.

234. GM engaged in unconscionable commercial practices in failing to reveal material facts and information about the Oil Consumption Defect, which did, or tended to, mislead Plaintiffs and the Nationwide Class and Illinois Subclass about facts that could not reasonably be known by the consumer including but not limited to the fact that the Class Vehicles overconsumed oil.

235. GM deliberately withheld material facts—such as that its Class Vehicles burned through oil and had the tendency to stall from Plaintiffs and the Nationwide Class and Illinois Subclass with the intent that Plaintiffs and the Nationwide Class and Illinois Subclass members rely upon the omission.

236. GM made material representations and statements of fact to Plaintiffs and the Nationwide Class and Illinois Subclass members that resulted in Plaintiff and the Nationwide Class and Illinois Subclass reasonably believing the state of affairs to be other than what it actually was, such as that its Class Vehicle would indicate that an oil change is necessary with a “Change Engine Oil Soon” message, which is not the case. Plaintiffs never saw any “Engine Oil Low” or “Change Engine Oil Soon” throughout their entire ownership of their Class Vehicles. GM’s representations in their owners manuals that says their vehicles are supposed to do so is deceptive.

237. GM intended that Plaintiffs and the other members of the Nationwide Class and Illinois Subclass members rely on their misrepresentations and omissions described above, so that Plaintiffs and other class members would purchase the Class Vehicles.

238. Had GM disclosed the omitted material or not misrepresented the characteristics of the Class Vehicles, Plaintiffs and other members of the Nationwide Class and Illinois Subclass would not have purchased or leased the Class Vehicles or would have paid less for them.

239. The foregoing acts, omissions and practices proximately caused Plaintiffs and the other members of the Nationwide Class and Illinois Subclass to suffer actual damages in the form of, inter alia, loss of the benefit of the bargain, diminution of value, the cost to repair each Class Vehicle's engine without compromising each Class Vehicle's performance.

240. GM's conduct was knowing, intentional, and malicious, and demonstrated a complete lack of care and recklessness and was in conscious disregard for the rights of Plaintiffs and the Nationwide Class and Illinois Subclass Members.

241. As a direct and proximate result of GM's unfair and deceptive trade practices, Plaintiff and the other Class members have suffered ascertainable loss and actual damages. Plaintiffs and the other Class members who purchased or leased the Class Vehicles would not have purchased or leased the Class Vehicles, or, alternatively, would have paid less for them had the truth about the Oil Consumption Defect been disclosed. Plaintiffs and the other Class members also suffered diminished value of their vehicles at the point of sale. Plaintiffs and the other Class members are entitled to recover actual damages, attorneys' fees and costs, and all other relief allowed under 815 Ill Comp. Stat. 505/1, *et seq.*

### **THIRD CAUSE OF ACTION**

#### **Breach of Implied Warranty (On Behalf of the Proposed Nationwide Class)**

242. Plaintiffs hereby incorporate by reference the allegations contained in the preceding paragraphs of this Complaint.

243. GM was at all relevant times the manufacturer, distributor, warrantor, and/or seller of the Class Vehicles. GM knew or had reason to know of the specific use for which the Class Vehicles were purchased.

244. GM provided Plaintiffs and Class Members with implied warranties that the Class Vehicles were merchantable and fit for the ordinary purposes for which they were sold.

245. However, the Class Vehicles are not fit for their ordinary purpose of providing reasonably reliable and safe transportation because, *inter alia*, the Class Vehicles and their engines contained the Oil Consumption Defect. Therefore, the Class Vehicles are not fit for their particular purpose of providing safe and reliable transportation.

246. The problems associated with the Oil Consumption Defect, such as engine stalls, the engine running hot, spark plug fouling, engine misfires, unexpected loss of power, the vehicle jerking and other problems as discussed herein pose enough of a safety risk such that the vehicles do not provide safe, reliable transportation, and thus breach of the implied warranty of merchantability. These problems are exacerbated by the frequent failure of the oil pressure indicator to properly function and alert or warn plaintiffs of the dangerously low levels of oil in the engine, which constitutes a further breach of the implied warranty.

247. GM impliedly warranted that the Class Vehicles were of merchantable quality and fit for such use. These implied warranties included, among other things: (i) a warranty that the Class Vehicles and their engines were manufactured, supplied, distributed, and/or sold by GM were safe and reliable for providing transportation and would not consume an abnormally high amount of oil between scheduled oil changes; and (ii) a warranty that the Class Vehicles and their engines would be fit for their intended use while the Class Vehicles were being operated.

248. Contrary to the applicable implied warranties, the Class Vehicles and their engines, at the time of sale and thereafter, were not fit for their ordinary and intended purpose of providing Plaintiffs and Class Members with reliable, durable, and safe transportation as a result of the Oil Consumption Defect. GM's actions, as complained of herein, breached the implied warranties that the Class Vehicles were of merchantable quality and fit for such use.

249. As a result of GM's breaches of implied warranties, Class members did not receive the benefit of their bargain and suffered damages at the point of sale stemming from their overpayment for a Class Vehicle with a latent safety defect.

#### **FOURTH CAUSE OF ACTION**

##### **Common Law Breach of Express Warranties (On behalf of the Proposed Nationwide Class)**

250. Plaintiffs hereby incorporate by reference the allegations contained in the preceding paragraphs of this Complaint.

251. In the course of selling the Class Vehicles, GM expressly warranted in writing that the vehicles were covered by certain warranties, including the Class Vehicles' Limited Warranties and GM's express warranty such as that it provided to Plaintiff.

252. GM breached its express warranties to repair defects in materials and workmanship of any part supplied by GM. GM has not repaired, and has been unwilling to reasonably repair, the Oil Consumption Defect.

253. Furthermore, the express warranties to repair defective parts, fail in their essential purpose because the contractual remedy is insufficient to make Plaintiffs and Class Members whole and because GM has failed and/or has refused to adequately provide the promised remedies within a reasonable time.

254. Accordingly, recovery by Plaintiffs is not limited to the express warranties of repair to parts defective in materials or workmanship, and Plaintiffs seek all remedies as allowed by law.

255. Also, as alleged in more detail herein, at the time that GM warranted and sold the Class Vehicles it knew that the Class Vehicles did not conform to the warranties and were inherently defective, and GM wrongfully and fraudulently misrepresented and/or concealed material facts regarding the vehicles. Plaintiffs and Class Members were therefore induced to purchase the Class Vehicles under false and/or fraudulent pretenses. The enforcement under these circumstances of any limitations whatsoever precluding the recovery of incidental and/or consequential damages is unenforceable.

256. Moreover, many of the damages flowing from the Class Vehicles cannot be resolved through the limited remedy of “replacement or adjustments,” as those incidental and consequential damages have already been suffered due to GM’s fraudulent conduct as alleged herein, and due to their failure and/or continued failure to provide such limited remedy within a reasonable time, and any limitation on Plaintiffs’ remedies would be insufficient to make Plaintiffs whole.

257. GM was provided notice of these issues by numerous complaints, including Plaintiffs’ pre-suit correspondence and numerous other customer complaints regarding the Oil Consumption Defect before or within a reasonable amount of time after the allegations of the defect became public.

258. As a direct and proximate result of GM’s breach of express warranties, Plaintiffs and Class Members did not receive the benefit of their bargain and suffered damages at the point the point of sale stemming from their overpayment for a Class Vehicle with a latent safety defect.

### **RELIEF REQUESTED**

Plaintiffs, individually and on behalf of all others similarly situated, request the Court enter judgment against GM, and accordingly requests the following:

- a) An order certifying the proposed Class and Sub-Class and designating Plaintiffs as named representatives of the Classes and designating the undersigned as Class Counsel;
- b) A declaration that GM is financially responsible for notifying all Class Members about the defective nature of the Class Vehicles and their engines;
- c) An order enjoining GM from further deceptive distribution, sales, and lease practices with respect to their Class Vehicles; to remove and replace Plaintiff and Class Members' engines with a suitable alternative product; and repair all other damages to the Class Vehicles caused by the defective engines;
- d) A further order enjoining GM from the conduct alleged herein, including an order enjoining GM from concealing the existence of the Oil Consumption Defect during distribution, sales, and advertisements, as well as during customer and warranty service visits for the Class Vehicles;
- e) An award to Plaintiffs and Class Members of compensatory, actual, exemplary, and statutory damages, including interest, in an amount to be proven at trial;
- f) A declaration that GM must disgorge, for the benefit of Plaintiffs and Class Members, all or part of the ill-gotten profits it received from the sale or lease of their Class Vehicles, or make full restitution to Plaintiffs and Class Members;
- g) An award of pre-judgment and post-judgment interest, as provided by law;
- h) Leave to amend the Complaint to conform to the evidence produced at trial;

- i) A recall of all Class Vehicles; and
- j) Such other relief as may be appropriate under the circumstances.

**DEMAND FOR JURY TRIAL**

Plaintiffs, on behalf of themselves and all others similarly situated, hereby demand a trial by jury as to all matters so triable.

Dated: April 10, 2018

s/ Gregory F. Coleman  
Gregory F. Coleman (TN014092)  
(Admitted to Trial Bar)  
Adam A. Edwards (*pro hac vice* to be filed)  
Mark E. Silvey (*pro hac vice* to be filed)  
GREG COLEMAN LAW PC  
800 S. Gay Street, Suite 1100  
Knoxville, TN 37929  
Telephone: (865) 247-0080  
Facsimile: (865) 522-0049  
greg@gregcolemanlaw.com  
adam@gregcolemanlaw.com  
mark@gregcolemanlaw.com

Daniel K. Bryson (*pro hac vice* to be filed)  
J. Hunter Bryson (*pro hac vice* to be filed)  
WHITFIELD BRYSON & MASON LLP  
900 W. Morgan St.  
Raleigh, NC 27603  
Telephone: (919) 600-5000  
Facsimile: (919) 600-5035  
dan@wbmlp.com  
hunter@wbmlp.com

Edward A. Wallace (6230475)  
Richard L. Miller II (6243507)  
Wexler Wallace LLP  
55 West Monroe, Suite 3300  
Chicago, IL 60603  
Telephone: 312-589-6272  
Facsimile: 312-346-0022  
eaw@wexlerwallace.com  
rlm@wexlerwallace.com

*Attorneys for Plaintiffs*

# **EXHIBIT A**



Chevrolet  
P.O. Box 909989  
Milwaukee, WI 53209-9989

*7PM*  
*(630) 518-4219*  
*Dusty*  
*7/19/13*



12313 2GNALDECEXB1236708 13 0016458  
SALLY J STAUBER  
407 DORSET PL  
GLEN ELLYN, IL 60137-5612



July 2013

Dear Sally J Stauber:

As the owner of a 2011 model year Chevrolet Equinox, your satisfaction with our product is very important to us.

This letter is intended to make you aware that on some 2011 model year Chevrolet Equinox vehicles, equipped with a 2.4L engine, the chrome layer on the balance chain pins may wear, allowing the chain to stretch. This would cause an engine noise, and if left untreated, could cause the chain to break, leading to engine damage.

In addition, the fuel pump plunger shaft seal may wear and allow fuel to leak into the crankcase, which would illuminate the Malfunction Indicator Light. This can cause engine run-on and/or the engine to run rough.

**Do not take your vehicle to your Chevrolet dealer as a result of this letter unless you believe that your vehicle has the condition as described above.**

**What We Have Done:** General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your 2011 model year Chevrolet Equinox, equipped with a 2.4L engine, within 10 years of the date your vehicle was originally placed in service or 120,000 miles, whichever occurs first, the condition will be repaired for you at **no charge**. Diagnosis or repair for conditions other than the condition described above is not covered under this special coverage program.


**What You Should Do:** If you believe that your vehicle has the condition described above, repairs and adjustments qualifying under this special coverage must be performed by a Chevrolet dealer. You may want to contact your Chevrolet dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

**Reimbursement:** If you have paid for repairs for the condition described in this letter, please complete the enclosed form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by July 31, 2014, unless state law specifies a longer reimbursement period.



If you have any questions or concerns that your dealer is unable to resolve, please contact the Chevrolet Customer Assistance Center at 1.800.222.1020 (TTY 1.800.833.2438).

We are sorry for any inconvenience you may experience; however we have taken this action in the interest of your continued satisfaction with our products.



Jim Moloney  
General Director - Customer & Relationship Services


Enclosure  
12313



# **EXHIBIT B**

# Ron Westphal

## CHEVROLET



Store: Westphal Chevrolet Address: 1425 West Odgen Avenue  
Aurora IL Phone: 630-898-9630

Customer Name: HERRINGTON, JENNIFER Address: , Phone: (630) 270-4183  
Year: 2011 Make: CHEVROLET Model: EQUINOX  
VIN: 2CNALPECSB6443760 Mileage: 83209 License:  
Repair Order #: 451568 Created: 02/20/2018 06:07 PM Tag #: 451568

Inspected and OK  May Require Attention Soon  Requires Immediate Attention  Not Inspected

### Pre Approved Items

No record found

### HVAC

No record found

### Wiper Blades

No record found

### Inspect for Visible Leaks

No record found

### Tires

No record found

### Original Customer Requests

POSSIBLE TIMMING CHAIN FAILURE

### Check Battery

No record found

### Check Brakes / Measure Front and Rear Linings

No record found

### Check Fluid Levels

No record found

### Inspect Visual Condition

No record found

## Inspection Estimates

Original Customer Requests	Status	Cost	Approved	Declined
<b>B: POSSIBLE TIMMING CHAIN FAILURE</b>				
REPL ENGINE ASSEMBLY	RED	\$6,900.00		X

Total Taxes and Fees	Cost	Approved	Declined
<b>Estimate Subtotal</b>	\$6,900.00	\$0.00	\$6,900.00
<b>Shop Fee</b>	\$18.63	\$0.00	\$18.63
<b>Taxes</b>	\$438.72	\$0.00	\$438.72
<b>Total</b>	\$7,357.35	\$0.00	\$7,357.35

**ALL PARTS ARE NEW OR FACTORY REBUILT UNLESS SPECIFIED OTHERWISE**

MISC. CHARGES - This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. [s.559.904(4)]. A charge is included for supplies used on your vehicle. Applicable supply items are: nuts, bolts, washers, tape, pins, solvents, carburetor cleaner, solder, wire sealers, lubricants, etc. The charge for both is equivalent to 12.5% of the total labor charge up to a maximum of 29.95. There will be no charge for storage.

The state of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s.403.718], and \$1.50 fee to be collected for each new or remanufactured battery sold in the state [s.403.7185].

LIMITED WARRANTY: The only warranties applying to the part(s) installed in accordance with the estimates are those that may be offered by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of products or service sold under the terms of this estimate. Parts and labor are guaranteed for 12 months unlimited mileage. Seller does not guarantee that the work performed in accordance with the estimate will correct any problem specified on the description of the complaint.

CUSTOMER HEREBY ACKNOWLEDGES RECEIPT OF ABOVE MENTIONED VEHICLE AND RECEIPT OF INVOICE HEREOF.

**A daily storage charge of \$50 shall begin three days after notification that repair work has been completed.**

**Payment Method:**  
 Cash  Check  Visa  
 MC  Amex

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW AND SIGN:  I UNDERSTAND THAT UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE, IF MY FINAL BILL WILL EXCEED \$100.00.  <input type="checkbox"/> I REQUEST A WRITTEN ESTIMATE.  <input type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG THE REPAIR COSTS DO NOT EXCEED \$_____. THIS SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.  <input type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE.  SIGNED: _____  DATE: _____	Proposed to be complete on	DATE   BY
	OTHER PERSON WHO MAY AUTHORIZE REPAIRS	PHONE
	ALL PARTS REMOVED WILL BE DISCARDED UNLESS REQUESTED BY THE CUSTOMER <input type="checkbox"/> SAVE	
	THE CHARGES FOR DIAGNOSING AND PREPARING THE INITIAL ESTIMATE WILL BE \$45.00, UNLESS NOTED OTHERWISE IN THE ESTIMATE BOX	
	THE CHARGE WILL BE BASED ON	<input type="checkbox"/> FLAT RATE <input type="checkbox"/> HOURLY RATE <input type="checkbox"/> BOTH
I hereby authorize the repair work hereinafter set forth to be done along with the necessary materials and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection  Signature _____		

Signature \_\_\_\_\_

# **EXHIBIT C**

# TECHLINK



July 2012, Volume 14, No. 7

## New Liquefied Petroleum Gas Chevrolet and GMC Cutaway Vans



The 2012 Chevrolet Express and GMC Savana 3500 and 4500 Cutaway Vans can now be equipped to operate on Liquefied Petroleum Gas (LPG). They include RPO K07 (Vehicle Fuel – Liquefied Petroleum Gas, Liquid) and RPO UFM( Parts Package – Complete Vehicle Kit, 3-Tank) or RPO UFP (Parts Package – Complete Vehicle Kit, 4-Tank).

### Vortec V8 Engine

The Vortec 6.0L V8 engine (RPO LC8) produces 332 horsepower and 370 lb.-ft. of torque. It has hardened intake and exhaust valves and exhaust valve seats for LPG fuel, providing the same durability as a gasoline engine.

Before the engine will start, vaporized LPG fuel in the fuel lines and injectors must be replaced with liquid fuel. A priming process is activated each time the ignition key is turned to ON. This can take eight or more seconds, depending on how long since the engine was last run. The LPG control module illuminates the Wait to Start indicator lamp on the center of the instrument panel during the purge cycle.

**TIP:** On the 3-tank system, if the LPG control module detects a fault within the input or control circuits of the system, the Wait to Start indicator lamp will be commanded to flash the appropriate code.

### Liquefied Petroleum Gas

LPG, the same gas that is delivered to homes for domestic utility use, is mainly propane — a highly flammable, colorless gas. An odor additive enables detection by smell. Propane should never be smelled and a hissing sound should not be heard, except during refueling.

The fuel gauge has been calibrated to LPG pressure and will display full at approximately 36 gallons (136 L) for the 3-tank system and 58 gallons (220 L) for the 4-tank system. LPG quantity is affected by changes in fuel temperature and fuel pressure.

continued on page 2

## TECHLINK

Contents	
New LPG Chevrolet and GMC Cutaway Vans . . . . .	1
Excessive Oil Consumption . . . . .	2
New Water Pump Bolts and Torque Specification . . . . .	4
Inoperative Auto Door Locks . . . . .	4
Tire Pressure Monitor Conditions . . . . .	4
HVAC Mode Doors Inoperative . . . . .	4
Inoperative Fuel Gauge, Hard Start Condition . . . . .	5
Replacing a Power Steering Cooler . . . . .	5
Rear Frame Rail Sectioning Instructions . . . . .	5
Volt No Charge Condition . . . . .	6
Updated GM Accessory Installation Information . . . . .	6
Sensing and Diagnostic Module Setup Procedure . . . . .	7
Rear Defogger Inoperative . . . . .	7
Updated Volt Tire Pressures . . . . .	7
Poor Sound Quality from Speakers . . . . .	7
Car Issues . . . . .	8
Thanks for Your Survey Participation . . . . .	8
Truck Issues . . . . .	9
Service Know-How . . . . .	9



Customer Care and Aftersales


# New Cutaway Vans – continued from page 1

It is normal to hear the fuel flowing while the engine is running with the ears close to the pipes and other components. Do not confuse this with a hissing sound at fittings that may indicate a fuel leak.

**TIP:** The black diamond-shaped LPG label on the rear of the vehicle is necessary for compliance with regulations. DO NOT remove this label.

	3-Tank System	4-Tank System
<b>Fuel tank locations</b>	Tanks 1, 2 and 3, 13 x 34 inch each, behind rear axle	Tanks 1, 2 and 3, 13 x 34 inch each, behind rear axle. Tank 4, 11 x 77 inch, mid-ship
<b>System capacity</b>	36 gallons	58 gallons

The LPG system, including the tanks and tubing, has been designed to hold gas at a working pressure of 312.5 psi (2,154.6 kPa) and a burst pressure of 1,250 psi (8,618 kPa). It has also been tested for safety. Baffles are built into the tanks to keep the fuel pump submerged in liquid propane at all times.




LPG Tank Components (front tank of 3-tank system shown)

1. LPG fuel bypass loop, mounted to a T-fitting on the return port of the fuel tank
2. Connection for the fuel return line from the distribution block
3. LPG cut-off solenoid, mounted to the outlet port of the fuel tank
4. Fuel level sensor
5. Liquid propane service valve and port
6. Manual shut-off for the liquid propane service valve (handle not included)
7. Spitter valve. Used for visual verification of 80% fill
8. LPG bypass loop solenoid and valve
9. Manual shut-off valve for LPG bypass loop
10. Fuel tank fill port and behind it, inside the tank is the 80% stop fill valve
11. Fuel tank electrical wiring harness pass-through for the internal fuel pump
12. Fuel tank access cover plate, for the internal components
13. Manual shut-off valve for the fuel return line

## System Components


**Fuel Tank Shields** – The tank shields protect the LPG tanks. If a tank shield is removed for any reason, always reinstall it before operating the vehicle.

**Overfilling Prevention Device** – This device is a float-actuated valve that prevents the tank from being filled more than



3-Tank LPG Component Location

1. Internal electric fuel pump
2. Pressure Relief Valve (PRV)
3. Fuel fill filter
4. Fuel supply filter
5. Fuel return line
6. Fuel distribution block
7. Fuel injector rail, passenger side of engine
8. Fuel supply line
9. Evaporative emission (EVAP) system
10. LPG fill cup



4-Tank LPG Component Location

1. Primary fuel pump (internal)
2. Scavenge fuel pump (internal)
3. Fuel fill lines
4. Rear fuel tank fill port and 80% stop fill valve
5. Pressure Relief Valve (PRV)
6. Fuel transfer pump or secondary transfer Liquid Propane Delivery Module (LPDM)
7. Fuel fill filter
8. Fuel fill line T-fitting
9. LPG fill cup, Sherwood Double Back Check Fill Valve, and fuel fill line
10. Transfer fuel line and port
11. Main fuel tank (mid-ship tank) fill port and transfer fuel line fill port
12. Pressure Relief Valve (PRV)
13. Electrical wiring harness
14. Liquid Propane Control Module (LPCM)
15. Fuel lines (concentric design)
16. Fuel rails and injectors
17. Liquid Propane Delivery Module (LPDM)

continued on page 3

## New Cutaway Vans –

continued from page 2

80%, to allow room for expansion. A properly functioning OPD valve stops gas flow immediately when the mechanism closes.

**Overflow Valves** – Every inlet and outlet valve on the propane tanks has a built-in overflow valve. If propane tries to exit the system at a higher rate than a calibrated amount, the difference in pressure closes the overflow valve and restricts the flow with a 0.080 in. (2 mm) diameter orifice. Once the difference in pressure is equalized, the overflow valve will open.

**Pressure Relief Valve** – If the pressure in the fuel tank exceeds 312.5 psi (2,154.6 kPa), the valve vents propane vapor to the atmosphere. The pressure will not get this high unless the tank has been overfilled or unless the tank is hotter than 140°F (60°C).

**Fuel Fill Filter** – The fuel fill filter is located on the frame rail between the front of the fuel tank and the fill valve. The filter traps particles larger than 3 microns.

**Fuel Supply Filter** – The fuel supply filter is mounted on the frame rail in the fuel supply line between the fuel tank and the fuel injector rails.

**Fuel Level Sensors** – A float and arm type fuel level sensor is used in the main fuel tank (4-tank model) and in the front tank of the rear tank assembly (both models).

**Fuel Pump** – The fuel pump is mounted inside of the fuel tank. The purpose of the fuel pump is to increase the line pressure of the liquid propane by 40-60 psi (275-414 kPa) over the internal tank pressure to ensure the propane is always maintained in a liquid state. The fuel pump inlet is submerged in liquid at all times by a baffle in the tank assembly. To service the fuel pump, remove the fuel tank internal components access cover plate.

**Fuel Lines (3-tank)** – The fuel lines are Type III LPG approved hoses with minimum permeability. The hoses are rubber-coated stainless steel braided to protect against chafing and have a burst pressure rating of 1,750 psi (12,066 kPa)

**Fuel Lines (4-tank)** – The fuel lines consist of two flexible hoses, one inside of the other. The inner line supplies liquid propane to the injectors and the area between the inner line and the outer line is the fuel return passage.

**Fuel Injectors** -- Each fuel injector has a supply passage and a return passage. A passage between them is restricted by a cooling bushing. As liquid propane passes through the cooling bushing, pressure drops, the propane vaporizes and cooling occurs. This maintains the fuel in a liquid state, regardless of the outside temperature.

**Fuel Transfer (4-tank model only)** – On the 4-tank system, the main tank controls all fuel delivery to the fuel injectors. When the liquid propane control module senses a difference in fuel level between the tanks, the secondary supply valve opens and the secondary fuel pump operates. Liquid propane is pumped from the rear tanks into the main tank.

**EVAP System** – The conventional EVAP control system has been disabled, with the exception of the EVAP purge solenoid valve. All EVAP DTCs also have been turned off, so there is no scan tool support. A unique EVAP sub-system maintains compliant levels of evaporative emissions.

### LPG Maintenance Schedule

The LPG engine vehicle is designed for routine maintenance (fluids, filters, etc.) similar to gasoline engine vehicles.

The LPG fuel system requires replacement of the LPG fuel fill filter and LPG in-line fuel filter every 30,000 miles (48,280 km).

### Training

For more information about the LPG system, refer to #PI0722 and view the Web-based training course 16240.65W, Liquefied Petroleum Gas (LPG) Fuel Systems, available at [www.gmtraining.com](http://www.gmtraining.com).

☺ Thanks to Sherman Dixon and Chris Graham

## Excessive Oil Consumption

Excessive oil consumption may be noticed on some 2010 Equinox and Terrain models equipped with the 2.4L direct-injected 4-cylinder engine (RPO LAF). In most cases, the oil consumption rate will be one quart or more every 1,000 miles (1,609 km). This condition may not be evident until the vehicle has accumulated 20,000 miles (32,187 km) or more. It may appear earlier if the drive cycle of the vehicle mainly consists of short trip driving (more thermal-cycles). Upon inspection, excessive oil in the fresh air side of the PCV system due to excessive crankcase pressure and blow-by may be noted. In addition, all four spark plugs will have obvious/excessive oil deposits on them.

If this condition is encountered, remove the spark plugs and inspect them for obvious/excessive oil deposits. If there is no sign of oil deposits on the spark plugs, perform an oil consumption test as outlined in the latest version of Bulletin #01-06-01-011 before proceeding.

If excessive oil consumption is verified by inspecting the spark plugs and/or performing an oil consumption test, perform the appropriate Service Information diagnosis for oil consumption and repair as necessary. If a single spark plug has obvious/excessive oil deposits, inspect the related valve seals to ensure that they are not missing, damaged, or torn and replace them as needed.

If the Service Information diagnostics does not isolate the cause of the condition and no obvious valve seal conditions are found, inspect the cylinder walls for obvious vertical "zebra stripes" as shown in the photo. In most cases, the cylinder head will have to be removed for inspection because these stripes may be hard to see with a bore scope. They also may not be apparent until the cylinder walls are cleaned with contact cleaner.



Vertical "zebra stripes" on the cylinder walls

If these stripes are NOT present, continue to follow the Service Information procedures and diagnosis to determine if there is another cause for the oil consumption, such as stuck rings, damaged rings, etc.

If these stripes ARE present, replace the engine using the latest part number listed in the parts catalog since this engine does not have serviceable cylinder liners like some of the other Ecotec engines. Before ordering the replacement engine, refer to #PIP5025 for additional information regarding engine replacement approval and installation.

☺ Thanks to James Parkhurst

## New Water Pump Bolts and Torque Specification


A new water pump fastening procedure has been implemented on all High Feature V6 engines (2.8L, 3.0L, and 3.6L) on all models (2004-2013 model years) to help reduce the potential for water pump gasket leaks. This new procedure requires NEW bolts to be used when attaching a water pump. It also requires a third pass with an additional 45 degree turn when tightening the bolts.

The new torque procedure puts the bolts into yield, so the bolts MUST be replaced when they are removed. Old/reused bolts will break if reinstalled. The following procedure applies to all model years and all RPOs of the HFV6 engine.

1. Ensure that the engine front cover and water pump are clear of old gasket material.

2. Ensure that the water pump mounting bolt holes in the front cover are completely clean and dry.
3. Place a new water pump gasket on the water pump.
4. Place the water pump in position on the front cover.
5. Install the water pump bolts finger tight.
6. Tighten the water pump bolts in sequence to 10 N·m (89 lb. in.).
7. Tighten the water pump bolts a second pass in sequence to 10 N·m (89 lb. in.).
8. Tighten the bolts a final pass in the sequence shown an additional 45 degrees.

🙏 Thanks to Andy Waddell




## Inoperative Auto Door Locks

The auto door lock/unlock feature may be inoperative and/or the power locks cycle on some 2012 LaCrosse and 2013 Malibu models. DTCs B3125 (Driver Door Only Unlock Circuit Short to Ground), B3130 (All Doors Unlock Circuit Short to Ground) and B3135 (All Doors Lock Circuit Short to Ground,) symptom code 02, may be set.

The 2012 LaCrosse and 2013 Malibu share the same Drivers Door Latch part number, but the linkages that connect the latch to the door key lock cylinder, lock button and external door handle are different for each model. These conditions may be present if a vehicle happens to be built with the incorrect linkage or linkages.

The illustration shows the shape of all linkages. Visually inspect the linkages and compare to the illustration to ensure the correct linkages are installed.

🙏 Thanks to Christopher Crumb



LaCrosse linkages are indicated in purple (1) and Malibu linkages are indicated in yellow (2).

## HVAC Mode Doors Inoperative

On a 2012 Enclave, Traverse or Acadia equipped with the automatic or manual HVAC system, the front or rear HVAC mode doors may be inoperative or may not function properly. DTC B3779 08 (Air Flow Control/9 Circuit Actuator Stalled) and other HVAC-related DTCs may be present.

The HVAC mode doors may not have been "learned" properly when the vehicle was built. Before replacing any components, attempt the Actuator Recalibration Procedure for the mode doors following the procedure in appropriate Service Information. If this does not correct the condition, continue with diagnosis and repair as necessary.

🙏 Thanks to Jim Miller

## Tire Pressure Monitor Conditions

Some 2008 Aveo and G3/Wave models may have one or more of the following Tire Pressure Monitor (TPM) conditions:

- Unable to enter TPM Learn Mode
- The battery light is inoperative with the key on, engine off
- DTC C0779 (Unregistered ID Code) is set in the TPM Module

With the key on, engine off, check voltage on pin 7 of the TPM module. The reading should be 0.0 volts with the generator connector plugged in.

If battery voltage is present, ground pin B at the generator using a suitable terminal or probe and evaluate the battery light for proper operation on the instrument cluster. If the battery light is inoperative, check for an open in the brown circuit between the generator and the TPM module. Also check for proper operation of the voltage regulator internal to the generator.

If the condition is no longer present after grounding Pin B at the generator connector, replace the generator and verify repairs.

🙏 Thanks to Bryan Brunner and Charles Hensley

## Inoperative Fuel Gauge and Hard Start/No Start Condition

Some 2008-2012 Enclave, 2009-2012 Traverse, 2007-2012 Acadia and 2007-2010 Outlook models may exhibit one or more of the following conditions:

- Engine is hard to start
- Engine will not start
- Engine starts, then stalls
- Fuel gauge is inoperative or fluctuates
- Service Engine Soon/Check Engine light is illuminated

These conditions, which may be intermittent and have various DTCs set, may be due to the fuel tank harness to body harness retainer slipping on the tubing, putting pressure on the harness and causing connector X305 to become partially separated or not fully seated.

Inspect connector X305 to make sure that it is fully seated. If the connector is not fully seated, inspect the terminals at connector X305 for corrosion. If the terminals show signs of corrosion, replace the corroded terminals.

Remove the wire harness retaining clip from the steel lines and reposition it in front of the steel line support to prevent it from sliding.

🙏 Thanks to James Miller



Connector X305




Move the wire harness retaining clip from the steel lines (1) to in front of the steel line support (2).

## Replacing a Power Steering Cooler

When replacing a leaking or damaged power steering cooler on a 2008-2012 Enclave, 2009-2012 Traverse, 2007-2012 Acadia or 2007-2010 Outlook, it is critical to replace the cooler without introducing a lot of air into the system.

When replacing a power steering cooler, first block off the hoses near the cooler connection with the appropriate clamps. Next, disconnect the cooler from the lines and remove the cooler.



Clamp the hoses (A, B) before disconnecting the power steering cooler (C).

Pre-fill the new cooler on the bench and cap off the pre-filled cooler ends for installation.

Install the new pre-filled cooler on the vehicle and remove the clamps on the hoses.

Once installation is complete, be sure to follow the Power Steering System Bleed Procedure in the appropriate Service Information

🙏 Thanks to James Miller


## Rear Frame Rail Sectioning Instructions

When sectioning the rear frame rail on a 2008-2012 Malibu, there may not be any die marks on the vehicle frame rail or the new part as indicated in Service Information. The die marks are not present because the exhaust hanger is attached to the frame where they would have been.

Locate the section that is about 60 mm wide between the exhaust hanger and the rear slot in the rail. Then, follow the sectioning directions in the appropriate Service Information procedure.

**TIP:** It is best to cut rearward of the bracket because of the flange change on the top of the rail.

🙏 Thanks to Christopher Crumb





Frame rail sectioning

## Volt No Charge Condition

A no-charge condition may be found on some 2011-2012 Volts when using either the stationary 240V or the 120V charger. DTC P0D26 (Battery Charger System Precharge Time Too Long) may be set in the Hybrid Powertrain Control Module (HPCM) 2.

If a no-charge condition is experienced, follow these steps:

1. Check the last 8 digits of the VIN. If it is lower than VIN BU100954, perform the latest version of #PIP4875 to program the HPCM 2, along with the other modules. For vehicles built after VIN BU100954, proceed to step 3.
2. If the condition returns or the vehicle has already had #PIP4875 performed, perform step 3.
3. Plug in the 120V charger and note the behavior of the charge indicator light on the top of the instrument panel and the lights on the charge cord set. If the light on the instrument panel is not steady green during a charging event, and the two upper charge cord set lights are steady green, record a GDS 2 snapshot from the HPCM 2 monitoring the Battery Charger Control Module Data.



4. Review the snapshot and monitor the proximity detection signal for erratic operation during charging. Also manipulate the charge cord coupler (handle) in different directions and monitor for proximity voltage changes.
5. Refer to the following two photos that show a good proximity signal and a proximity signal that is erratic.
6. If the snapshot shows the erratic signal, and/or the condition changes when the charge cord coupler (handle) is manipulated, or the proximity signal does not drop to a steady 1.49 volts, inspect the charge port receptacle and wiring.
7. Check the charge port receptacle connector for signs of water intrusion or corrosion in both the vehicle harness side and charge port side. If a condition is found, replace the receptacle and harness.
8. If no water or corrosion is found, test the resistance of all the charge port receptacle circuits to each other while disconnected from the Onboard Battery Charge Module (OBCM), the HPCM 2 and the charge port receptacle. All circuits should read open. If they do not, inspect the harness or connector for a short. Refer to the appropriate Service Information.
9. Check resistance and load test circuits 3837, 3838 and 3952 between the receptacle and the OBCM to isolate any charge cable wiring related concerns.
10. If none of the above lead to a resolution, continue with the published diagnostics for DTC P0D26.

☺ Thanks to Charles Krepp

## Updated GM Accessory Installation Information

The installation procedures of several GM Accessories have been updated recently. Complete accessory installation information can be found in the appropriate Service Information.

### Fullsize Truck Inclination Sensor (P/N 17800432)

The mounting location of the sensor has been moved to the top of the BCM bracket. This reduces false alarm activation due to significant temperature differences between the vehicle cabin and outside ambient temperatures. The updated instructions can be found in the online Service Information – Accessory Manual (Theft Deterrent Vehicle Inclination Sensor Package Installation).

### Verano Spoiler

(P/Ns 22791799 – 22791805)

The torquing sequence of the spoiler fasteners during installation has been updated. Failure to torque in the specified sequence can result in a “warped” appearance or breaking of the mounting studs. For updated instructions, go to the online Service Information – Accessory Manual (Rear End Spoiler Package Installation).

### Malibu Molded Splash Guards

(P/N 22864060 – Rear/20995548 – Front)

The instruction sheets are being updated to clarify the installation steps to install the rear splash guards on new 2013 Malibu models. It is necessary to drill all holes used to mount the rear molded splash guard. There is an existing lower fastener on the vehicle that should not be used to install the rear molded splash guard. If the existing hole/fastener is used, it will skew the splash guard and create a gap condition at the top of the splash guard. The updated instruction sheets are viewable in the online Service Information – Accessory Manual (Molded Splash Guard Installation).

### Sonic Hatchback Spoiler Installation

(P/Ns 95942507, 95942508, 95942509, 95942510)

The initial shipments of parts do not include the installation sheet. Refer to the online Service Information – Rear End Spoiler Replacement for the removal and installation procedure. The existing fasteners used for the Original Equipment (OE) spoiler (4 screws and 3 nuts) can be reused to install the accessory spoiler. The Service Information procedure calls out the torque specifications for all fasteners.

☺ Thanks to Ann Briedis



GM TechLink is published for all GM retail technicians and service consultants to provide timely information to help increase knowledge about GM products and improve the performance of the service department.

**Publisher:**

Diana Sancya  
GM Customer Care and Aftersales  
✉ Diana.Sancya@gm.com

**Editor:**

Lisa G. Scott  
GM Customer Care and Aftersales  
✉ Lisa.G.Scott@gm.com

**Technical Editor:**

Mark Spencer  
✉ mspencer@gpworldwide.com

**Production Manager:**

Marie Meredith

**Desktop Publishing:**

5by5 Design LLC  
✉ dkelly@5by5dzn.com

**FAX number:** ☒

1-248-729-4704

**Write to:** ✉

TechLink  
PO Box 500  
Troy, MI 48007-0500

**GM TechLink on the Web:** 🖥️

GM GlobalConnect

General Motors service tips are intended for use by professional technicians, not a "do-it-yourselfer." They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the information applies to your vehicle or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

Inclusion in this publication is not necessarily an endorsement of the individual or the company.

Copyright© 2012 General Motors  
All rights reserved.

## Sensing and Diagnostic Module Setup Procedure

On the 2013 Chevrolet Malibu Eco model, the SIR MIL may flash after the Sensing and Diagnostic Module (SDM) was reprogrammed if the SDM Setup is not able to be performed. No DTCs will set.

After successfully programming the SDM, the SDM must be allowed to go to sleep before the SDM Setup procedure can be attempted. Switch off the ignition, remove

the key, and open and close the driver's door to disable Retained Accessory Power. This will allow the SDM to go to sleep and write new data to memory.

At this point, technicians may now enter the vehicle, turn the ignition switch on and perform the SDM Setup procedure.

🙏 Thanks to Christopher Crumb

## Rear Defogger Inoperative

The rear defogger may be inoperative or the rear window glass may not clear on some 2012 Sonic models.

Inspect the terminals at the rear defogger grid. Be sure they are fully seated and that the terminals are not backed out of their connectors. Repair any loose terminals and/or connectors at the rear defogger grid. Do not replace the BCM.

🙏 Thanks to Ernest Haller

## Updated Volt Tire Pressures

The tire pressure specification on the 2012 Volt and beyond has been updated. The tire pressures should be set at 38 psi. The updated specification is reflected on the Tire and Loading Information label located on the driver's door pillar.

If the tire pressure monitor indicator icon is continuously illuminated after the instrument cluster bulb check is completed, a low tire pressure condition may be present. Check the tires for damage or leaks and inflate the tires to the correct specification.

🙏 Thanks to Ashmi Haria

## Poor Sound Quality from Speakers

There may be a poor sound quality condition on some 2013 Malibu models equipped with the navigation radio (RPO UEW):

- A vehicle equipped with base speakers (RPO UW6) may be muted (low volume) or there may be poor sound quality from the speakers
- A vehicle equipped with an amplifier (RPO UQA) may be over-boosted (high volume) and may exhibit distortion or poor sound quality from the speakers



Navigation radio

The radio may have been programmed with the wrong calibration during assembly, causing these poor sound quality conditions.

Reprogram the radio (silver box) with the correct calibration listed below using TIS2WEB:

- Navigation Radio (RPO UEW) with base speakers (RPO UW6) – Correct PN 20945590
- Navigation Radio (RPO UEW) with amplifier (RPO UQA) – Correct PN 20945591

🙏 Thanks to Christopher Crumb



## Car Issues – Fix It Right the First Time

Model Year(s)	Vehicle Line(s)/Condition	Do This	Don't Do This	Reference Information/Bulletin
2012	Sonic — Receiving and cleaning dot on outside rear view mirror glass	Use high performance body solvent (Acrysol) and allow it to soak for 5 minutes before attempting to remove the dot on the outside rearview mirror glass	Replace the outside rearview mirror glass or assembly	PI0738
2010-2013	Malibu, Verano, Sonic, VOLT, Regal, SRX, Equinox, LaCrosse, Cruze — Rear doors intermittently will not open from inside and/or Electric Child Lock (ECL) LED light in the ECL switch flashing	Review with the owner that the handles must be released when the ECL button is pressed	Replace rear door latches	PI0737
2010-2012	Malibu — Power Steering or Reduced Power Message displayed in DIC, DTC C0475 or P2138 set	Inspect for and repair the water leak that caused the concern, look for signs of corrosion in electrical connectors	Replace the accelerator pedal or power steering control module without inspecting for water leak	PI0116B
2008-2012	CTS, CTS Sport Wagon, CTS-V, CTS-V Sport Wagon — Rear door glass lowers without window switch activation, especially after car wash or rain	Remove door trim fastener and seal per PI	Replace door switch regulator	PI0734
2012	Regal, LaCrosse — MIL On, DTCs C0187, C0287 and C0196 set or stored in history	Reprogram the EBCM	Replace the yaw rate sensor or EBCM	PI0730
2012	Impala — MIL On, various DTCs set, IPC inoperative, display and/or BCM fuse blown	Follow bulletin to lift up / flip over harness to properly inspect all the wiring	Replace parts without inspecting harness	PI0631C
2011	Impala — Pop type noise when turning left or right	Inspect for engine oil leak	Don't overlook a possible leak prior to replacing any parts	PI0736
2012	Regal — Touch screen functions inoperative or radio cycles through screens without user input	Replace the trim panel	Replace the radio	PI0641A
2011-2012	Sonic, Cruze — Information for No Trouble Found turbochargers returned to Warranty Parts Center	Check oil feed pipe and oil return pipe when replacing turbo charger	Replace turbocharger just for cracks at the waste gate	PI0675A
2011-2012	VOLT, Sonic, Cruze — Information on servicing plastic components and transferring on a new service engine	Check condition of plastic parts when repairing vehicle for over heat condition	Transfer parts without inspecting for damage	12-06-01-005
2011-2012	Sonic, Cruze — Coolant leak at thermostat housing to cylinder head	Inspect seals for rolling and replace seals	Replace thermostat housing or thermostat	PI0721A
2010-2012	Camaro — Rear axle chatter noise on low speed turns	Replace the rear differential axle shaft seals and install Dexron oil	Replace the rear differential or the limited slip clutches	PI0137C
2012	Camaro — Passenger-side instrument panel ZL1 emblem peeling/falling off	Wait for the new part to be released. A bulletin will be released to advise on part availability	Replace the appliqué with current SPO stock. The stock is being cleared and new stock will be available June 30, 2012. The part number will not change	PI0739
2006-2011	DTS, Allure — Side door sticks or may intermittently become inoperative from outside door handle in higher temperatures	Replace door outside handle and latches	Adjust the door handle or latch	09-08-64-035D

## Thanks for Your Survey Participation

The GM Electrical Diagnostic Workgroup would like to thank the technicians who took part in the Electrical Diagnostic three-question survey.

Because of the positive responses, in the future we will start adding the additional terminal information for the end-to-end

continuity testing in the secondary test step. In some instances, this detail may still not be supported because of terminal complexity at the control module; in which case, the schematic will still need to be referenced to identify the correct terminal ID to conduct testing.

Thanks for helping us make the right decisions when it comes to enhancing the electrical diagnostic procedures.

🙏 Thanks to Dave Nowak and the GM Electrical Diagnostic Workgroup



## Truck Issues – Fix It Right the First Time

Model Year(s)	Vehicle Line(s)/Condition	Do This	Don't Do This	Reference Information/Bulletin
2006-2009	G8, H2, Yukon XL Denali, Yukon XL, Yukon Denali, Yukon, Sierra, Suburban, Silverado, Corvette, Escalade EXT, Escalade ESV, Escalade, XLR, XLR-V, STS, — Slips in Reverse or Third, delayed Reverse or Drive engagement, DTC P0776, P2715, P2723, harsh 2-3 shifts	While making repairs on a 6L80 / MYC-equipped vehicle, replace the transmission fill tube	Repair and install the transmission on 6L80 / MYC-equipped vehicles without replacing the fill tube	09-07-30-004I
2007-2013	Escalade, Escalade ESV, Escalade EXT, Sierra, Silverado, Suburban, Tahoe, Yukon, Yukon XL — Loss of power door lock function on one or several doors	Repair door lock knob interference	Replace the door lock/actuator	12-08-64-001
2008-2012	Sierra, Silverado — Weak/Dead Battery, No start/battery drain, no crank with or without the following DTCs: U0140, U0151, U0164, U0168, U0214, U0155, U0184, U0194, U0198, B1019, U0170, C0561 in low speed modules	Check for the source of water leak if corrosion is found on RCDLR terminals	Replace the RCDLR without repairing the water leak	12-08-57-001
2007-2012	Tahoe - Police Pursuit Vehicle (PPV) — Engine mount clunk noise and/or leaking	Replace the hydraulic mount bushing with a solid mount bushing	Reinstall a hydraulic mount	12-06-01-004
2011	Escalade, Escalade ESV, Escalade EXT, Escalade, Escalade ESV, Escalade — Navigation radio will not display map data , message display is On	Order and install the 2012 MY navigation service compact flash card and load software into the radio	Replace the navigation radio	PI0504B
2011-2012	Escalade, Escalade ESV, Escalade EXT — Front door power window(s) operation slow, squeak, screech, squeal or scrape type noise	Remove the flashing from the window reveal molding/run channel area	Replace the molding or window regulator	PI0728
2012	Canyon, Colorado, Express, Savana, Sierra, Silverado — MIL with DTC P0741 set, harsh 1-2 shift	Replace the TCC enable solenoid and internal wiring harness	Replace the torque converter	PIP5009D

### Service Know-How

#### 10212.07D Emerging Issues July 12, 2012

To view Emerging Issues seminars:  
Log in to [www.gmtraining.com](http://www.gmtraining.com), select Service Know-How/TECHAssist from the menu, select Emerging Issues, and then Searchable Streaming Video to choose the current Emerging Issues seminar or past programs.



Customer Care and Aftersales

# **EXHIBIT D**

---

## 2.4L Ecotec Engine Oil Consumption

Posted on [August 6, 2013](#) by [blogadmin](#)

Excessive oil consumption on some 2010-2013 LaCrosse, Equinox, Terrain and 2011-2013 Regal models equipped with the 2 (RPOs LAF, LEA) does not require engine replacement. If excessive oil consumption is confirmed after an oil consumption test, pistons and piston rings should be installed.

### Piston Ring Coating

The top compression ring in the new kit has a more robust coating on it that is designed not to wear as quickly as the original. Tests indicate that it wears about 4-5 times longer than the original coating.

If the top compression ring is worn, it will allow combustion pressure past it, which causes the oil control rings to be less effective, resulting in excessive oil consumption.

On 2010-2011 vehicles built before March 2011, there is a strong correlation between leaking high pressure fuel pumps diluting the oil and causing the ring wear. Due to this, check the fuel pump, balance chain, balance chain tensioner and timing chain for the correct part numbers. The updated fuel pump has an enhanced seal.

If these updated parts have not been installed during a previous repair, they should be replaced when the pistons and rings are replaced. Use field action #12313 if the balance chain and/or fuel pump is replaced.

### Zebra Stripes

The pistons must be replaced because as the rings wear down, it starts to widen the piston ring grooves. The worn grooves will not seal the new rings correctly.

The "zebra" stripping on the bore surface (Fig. 1) is not an indication of a cylinder bore abnormality, but rather a transfer of material as it was worn down. The bores are still uniform and the new rings seal. The validation of the new ring pack was done on test blocks that had zebra striping. It's not necessary to do any surface treatment to the zebra striped bores when installing the new pistons and rings.



Fig 1

**TIP:** Use only plastic scrappers to clean the sealing surfaces of the engine. Cleaning wheels and pads will leave material in the groove. An indication that cleaning wheels/pads were used will be an engine that runs for 2,000–4,000 miles after the piston/ring replacement and then develops an oil pressure condition or rod/main bearing knock for a worn bearing.

Refer to Bulletin #13-06-01-003B for additional information, including several other parts — such as balance chain guides and chain guides — that should be inspected for excessive wear as well as normal wear markings of other components, such as the camshafts (Fig. 2) and roller follower.




Fig 2

– Thanks to Ron Caponey

## 2 Responses to 2.4L Ecotec Engine Oil Consumption

**Ed.** says:

August 12, 2013 at 10:15 am

On 2010 and 2011 vehicles built before March of 2011, verify that the high pressure fuel pump (P/N 12641847), balance chain (P/N 12645237), balance chain tensioner (P/N 12649233), and timing chain kit (P/N 12635447) have been installed in this engine in a previous repair. Refer to IVH and check the parts listed in the prior repairs. If these parts have not been installed, they should be replaced at the time that the piston and rings are replaced. If they have been replaced, do not replace them again. Engines in 2012 and 2013 vehicles do not need the balance chain or fuel pump inspected.

---

**rick** says:

August 9, 2013 at 5:13 pm

How do we know we are getting the updated high pressure fuel pump

# **EXHIBIT E**

## 2010 Chevy Truck Equinox AWD L4-2.4L

Vehicle » Technical Service Bulletins » All Technical Service Bulletins » Engine - Excessive, Abnormal Oil Consumption

### # 13-06-01-003D: Excessive Oil Consumption - Perform Oil Consumption Test and/or Install Piston and Piston Ring Kit - (Sep 10, 2013)

Subject: Excessive Oil Consumption - Perform Oil Consumption Test and/or Install Piston and Piston Ring Kit

Models: 2010-2013 Buick LaCrosse 2011-2013 Buick Regal  
2010-2013 Chevrolet Equinox  
2012-2013 Chevrolet Orlando (Canada Only)  
2010-2013 GMC Terrain  
Equipped with 2.4L Engine (RPOs LAF, LEA)

This bulletin has been revised to add the Orlando model and update the Warranty Information. Please discard Corporate Bulletin Number 13-06-01-003C.

#### Condition

Some customers may comment on excessive oil consumption and/or that they have to add oil between oil changes.

#### Correction

For this condition, technicians should perform an oil consumption test by following the latest version of Corporate Bulletin Number 01-06-01-011. Before starting the oil consumption test, verify the ECM has latest TIS2web calibrations to adjust the engine oil life monitor to a maximum of 7,500 miles (12,070 km) - Refer to Customer Satisfaction Bulletin # 12312.

Inspect for any obvious oil leaks that may explain the oil consumption concern and repair as necessary.


#### Important:

When checking the oil level with the oil dipstick design shown below, please note that the oil volume per notch is not linear due to the shape of the block. The upper notches (relative to the top of the handle) equal 0.24 quart (0.227 L) between each notch while the lower notches only equal 0.14 quart (0.132 L) between each notch. As a result, no oil will appear on the dipstick if it is low on oil by approximately 1.25 quarts (1.18 L) or more. When determining the oil consumption rate, the oil volume added to return it to the starting location is the total amount of oil consumed. The consumption rate must be documented on a repair order.

#### Notice:

Do not add too much oil. An overfill can lead to burn off of the excess oil. Advise the customer to wait until the oil is below the cross-hatched area at the tip of the dipstick before adding oil.





If the oil consumption test indicates that the rate of consumption is greater than 1 quart (0.946 L) of oil every 2,000 miles (3,200 km), note the oil consumption rate, the date that the ECM was reprogrammed and any repairs/diagnosis that you have performed.

The repair is to replace the pistons and rings. In some cases the bore surface may not have a uniform look to the finish (zebra stripes) as shown below. As a result, some technicians may question whether the engine should be repaired or replaced. After careful evaluation, GM Powertrain has determined that the new pistons and rings will perform correctly in bores that have this appearance so engine replacement should not be necessary. The cylinder bores do not need any machine or honing work performed on them. Refer to the picture below for acceptable surface finishes.

**Important:**

DO NOT use any abrasive wheels/ materials to clean any mating surfaces. Only Plastic scrapers should be used. Please refer to the latest version of Corporate Bulletin Number 00-06-01-012.

**Acceptable Cylinder that Does Not Appear Uniform (Zebra Stripes)**





While performing this repair on 2010 and 2011 vehicles built before March of 2011, it should be verified that the high pressure fuel pump (P/N 12641847), balance chain (P/N 12645237), balance chain tensioner (P/N 12649233), and **timing chain** kit (P/N 12635447) have been installed in this engine in a previous repair. Refer to MVH and check the parts listed in the prior repairs. If these parts have not been installed, they should be replaced at the time that the **piston** and rings are replaced. If they have been replaced, do not replace them again. Engines in 2012 and 2013 vehicles do not need the balance chain or fuel pump inspected.

Also when performing this repair, several other parts should be inspected for excessive wear and/or damage and replaced if necessary:


- Balance chain guides
- **Timing chain guides**


**Important:**

DO NOT use any abrasive wheels/ materials to clean any mating surfaces. Only Plastic scrapers should be used. Please refer to the latest version of Corporate Bulletin Number 00-06-01-012.


**Note:**

Returned oil consumption engines have been reviewed at engine tear down. It has been determined that these components do not need to be replaced:





^Camshafts and roller follower will have wear markings. This is normal and do not need to be replaced (refer to picture above).



^Valves stems may have deposits build up on them. These deposits are characteristic of a direct inject engine. The valves stems do not need to be cleaned as they are not affecting engine performance (Refer to picture above).

^The **oil pump** does not need to be replaced as the low oil level operation did not damage the pump.

^The camshaft actuators do not need to be replaced at this time. The vehicle may have arrived with the engine knocking. If the oil level was 1-1/2 - 2 quarts low, it was the lack of oil causing the actuator noise.

^Rod bearings can be reused if there is not any excessive scoring, some light wear marks are acceptable

**Important:**

Rod bearings must be marked to identify the proper location to ensure bearings are returned to their

original positions.

The final step is to verify that ECM OLM calibration has been installed before the vehicle is returned to the customer.

**Important:**

DO NOT use any abrasive wheels/materials to clean any mating surfaces. Only Plastic scrapers should be used. Please refer to the latest version of Corporate Bulletin Number 00-06-01-012.

Part Number	Description
12646457	PISTON KIT, ENG
12659419	RING KIT, PSTN
12637166	GASKET KIT, CYL HD
12609291	SEAL, CM/SHF

Parts Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4080008*	Oil Consumption Test Setup	0.2 hr
4080178*	Piston, Connecting Rod and Bearing Replacement (Includes Oil Consumption Test)	9.5 hrs
Add	To Replace Fuel Pump (2010-2011 Models Built Prior to March 2011 Only)	0.7 hr
Add	To Replace Balance Shaft Chain and Tensioner (2010- 2011 Models Built Prior to March 2011 Only)	0.8 hr
Add	To Replace Timing Chain (2010-2011 Models Built Prior to March 2011 Only)	0.5 hr

\*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.

### Warranty Information

<p>GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.</p>		<p>WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION</p>
--	--	--

### Disclaimer

# **EXHIBIT F**



# Service Bulletin

File in Section: 06 - Engine

Bulletin No.: 13-06-01-003F

Date: May, 2014

## TECHNICAL

**Subject:** Excessive Oil Consumption – Perform Oil Consumption Test and/or Install Piston and Piston Ring Kit

**Models:** 2010-2013 Buick LaCrosse  
2011-2013 Buick Regal  
2012-2013 Buick Verano  
2010-2013 Chevrolet Equinox  
2012-2013 Chevrolet Captiva, Orlando (Canada Only)  
2010-2013 GMC Terrain  
Equipped with 2.4L Engine (RPOs LAF, LEA)

This bulletin has been revised to update the Parts Information. Please discard Corporate Bulletin Number 13-06-01-003E.

### Condition

Some customers may comment on excessive oil consumption and/or that they have to add oil between oil changes.

### Correction

For this condition, technicians should perform an oil consumption test by following the latest version of Corporate Bulletin Number 01-06-01-011. Before starting the oil consumption test, verify the ECM has latest TIS2web calibrations to adjust the engine oil life monitor to a maximum of 7,500 miles (12,070 km) — Refer to the latest version of Customer Satisfaction Bulletin #12312.

Inspect for any obvious oil leaks that may explain the oil consumption concern and repair as necessary.

**Important:** When checking the oil level with the oil dipstick design shown below, please note that the oil volume per notch is not linear due to the shape of the block. The upper notches (relative to the top of the handle) equal 0.24 quart (0.227 L) between each notch while the lower notches only equal 0.14 quart (0.132 L) between each notch. As a result, no oil will appear on the dipstick if it is low on oil by approximately 1.25 quarts (1.18 L) or more. When determining the oil consumption rate, the oil volume added to return it to the starting location is the total amount of oil consumed. The consumption rate must be documented on a repair order.

**Notice:** Do not add too much oil. An overfill can lead to burn off of the excess oil. Advise the customer to wait until the oil is below the cross-hatched area at the tip of the dipstick before adding oil.



3339530

If the oil consumption test indicates that the rate of consumption is greater than 1 quart (0.946 L) of oil every 2,000 miles (3,200 km), note the oil consumption rate, the date that the ECM was reprogrammed and any repairs/diagnosis that you have performed.

The repair is to replace the pistons and rings. In some cases the bore surface may not have a uniform look to the finish (zebra stripes) as shown below. As a result, some technicians may question whether the engine should be repaired or replaced. After careful evaluation, GM Powertrain has determined that the new pistons and rings will perform correctly in bores that have this appearance so engine replacement should not be necessary. The cylinder bores do not need any machine or honing work performed on them. Refer to the picture below for acceptable surface finishes.

**Note:** Use Piston Ring Compressor EN-47836 when installing rings.

**Important:** DO NOT use any abrasive wheels/materials to clean any mating surfaces. Only Plastic scrapers should be used. Please refer to the latest version of Corporate Bulletin Number 00-06-01-012.

### Acceptable Cylinder that Does Not Appear Uniform (Zebra Stripes)




3339531


While performing this repair on 2010 and 2011 vehicles built before March of 2011, it should be verified that the high pressure fuel pump (P/N 12641847), balance chain (P/N 12645237), balance chain tensioner (P/N 12649233), and timing chain kit (P/N 12635447) have been installed in this engine in a previous repair. Refer to IVH and check the parts listed in the prior repairs. If these parts have not been installed, they should be replaced at the time that the piston and rings are replaced. If they have been replaced, do not replace them again. Engines in 2012 and 2013 vehicles do not need the balance chain or fuel pump inspected.

The oil consumption may have clogged/ reduced PCV flow. The PCV system should be serviced.

Clean any ice/sludge/water/carbon out of the PCV pipes/hoses, the PCV nipple on the cam cover, the PCV orifice between the #2 and #3 intake runners (use a 1/16 inch drill bit as illustrated below).



3704956



3704955

### Legend


- (1) PCV orifice in the intake manifold

Also when performing this repair, several other parts should be inspected for excessive wear and/or damage and replaced if necessary:

- Balance chain guides
- Timing chain guides


**Important:** DO NOT use any abrasive wheels/materials to clean any mating surfaces. Only Plastic scrapers should be used. Please refer to the latest version of Corporate Bulletin Number 00-06-01-012.

**Note:** Returned oil consumption engines have been reviewed at engine tear down. It has been determined that these components do not need to be replaced:



3409678

- Camshafts and roller follower will have wear markings. This is normal and do not need to be replaced (refer to picture above).



3409680

- Valves stems may have deposits build up on them. These deposits are characteristic of a direct inject engine. The valves stems do not need to be cleaned as they are not affecting engine performance (Refer to picture above).

- The oil pump does not need to be replaced as the low oil level operation did not damage the pump.
- The camshaft actuators do not need to be replaced at this time. The vehicle may have arrived with the engine knocking. If the oil level was 1 1/2 - 2 quarts low, it was the lack of oil causing the actuator noise.
- Rod bearings can be reused if there is not any excessive scoring. Some light wear marks are acceptable.

**Important:** Rod bearings must be marked to identify the proper location to ensure bearings are returned to their original positions.

The final step is to verify that ECM OLM calibration has been installed before the vehicle is returned to the customer.

**Important:** DO NOT use any abrasive wheels/ materials to clean any mating surfaces. Only Plastic scrapers should be used. Please refer to the latest version of Corporate Bulletin Number 00-06-01-012.

### Parts Information

Part Number	Description
19303450	PISTON AND RING KIT, ENG (Set of 4)
12637166	GASKET KIT, CYL HD
12609291	SEAL, CM/SHF

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4080008*	Oil Consumption Test Setup	0.2 hr
4080178*	Piston, Connecting Rod and Bearing Replacement (Includes Oil Consumption Test)	9.5 hrs
Add	To Replace Fuel Pump (2010-2011 Models Built Prior to March 2011 Only)	0.7 hr
Add	To Replace Balance Shaft Chain and Tensioner (2010-2011 Models Built Prior to March 2011 Only)	0.8 hr
Add	To Replace Timing Chain (2010-2011 Models Built Prior to March 2011 Only)	0.5 hr

\*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.